APPROVED BY _

CONDITIONS OF APPROVAL, IF ANY:

Form approved. Budget Bureau No. 42-R1425.

DATE _

UNITED STATES DEPARTMENT OF THE INTERIOR

| | 5. LEASE DESIGNATION AND SERIAL NO. | | | | | |
|---|--|--|---|-----------|--|-----------------------------|
| | 14-20-603-247 | | | | | |
| | Y FOR PERMIT 1 | O DRILL, DEEPI | EN, OR PLUG B | ACK | 6. IF INDIAN, ALLOTTEE O | OR TRIBE NAME |
| la. TYPE OF WORK | LL 🛽 | DEEPEN 🗆 | PLUG BAC | 'к 🗀 | 7. UNIT AGREEMENT NA | ¥3 |
| b. TYPE OF WELL | | | | | SW-I-4192 | |
| WELL W | ELL OTHER | | Marie Siria | TU | 8. FARM OR LEASE NAME | |
| 2. NAME OF OPERATOR | C | la c li | JOE U | Pa | Ratherford Un | it |
| Phillips Oil | Company | | • | | 9. WELL NO. | |
| 3. ADDRESS OF OPERATOR D O Boy 202 | 20 Casper, WY 82 | 2602 | JAN 07 1985 | | #13-4 | |
| | | | | | 10. FIELD AND POOL, OR | |
| 1. LOCATION OF WILL (R. At SULLICE 1700) | eport location clearly and FSL, 960' FEL | in accordance with any 8 | DIVISIUN'UF' | | Greater Anet | |
| 2,00 | 102, 700 122 | UK, | GAS & MINING | | AND SURVEY OR ARE | A |
| At proposed prod. zon | e | | | | Sec. 13-T41S- | R23E |
| Same | AND DIDECTION PROM NEAR | REST TOWN OR POST OFFICE | · · · · · · · · · · · · · · · · · · · | | 12. COUNTY OR PARISH | 13. STATE |
| | | | | | | |
| Approximately D. DISTANCE FROM PROPERTY | J miles souther | east of Montezur | na Ureek, Utah | 17. NO. | San Juan OF ACRES ASSIGNED | Utah |
| LOCATION TO NEAREST PROPERTY OR LEASE I | r you west of | Ratherford 16. No | 1600 acres | | rhis WELL 40 acr | es |
| (Also to nearest drlg S, DISTANCE FROM PROP | INE, FT. g. unit line, if any) Unit | 64 east 19. PR | ROPOSED DEPTH | 20. вот. | ARY OR CABLE TOOLS | |
| TO NEAREST WELL, D OR APPLIED FOR, ON TH | RILLING, COMPLETED, " , , | 77 6456 | 5700' | | Rotary | |
| 21. ELEVATIONS (Show who | | | Washington Comments | 4 | 22. APPROX. DATE WOR | |
| 4645' Ungrade | | | r w | | First Quart | er 1985 |
| 3. | F | PROPOSED CASING ANI | CEMENTING PROGRA | M | | |
| SIZE OF HOLE | SIZE OF CASING | WEIGHT PER FOOT | SETTING DEPTH | | QUANTITY OF CEMENT | |
| 17-1/2" | 13-3/8" | 48# | 100' | 150 | sx (Circ to sur | face) |
| 12-1/4" | 9-5/8" | 36# | 1600' | 600 | sx (Circ to sur | face) |
| 8-1/2" | 7" | 23# & 26# | 5 7 00 ' | 600 | sx (T.O.C. Appr | ox 2000') |
| oil well, to | increase the ul | ill Ratherford I Itimate recovery ted daily and to | y from the Rath | | Creek Developm Unit. | ent |
| | | | OF UT/ OH, G/ DATE: / // | AH DI | THE STATE VISION OF MINING | |
| | | | BY: John | | | |
| N ABOVE SPACE DESCRIBE one. If proposal is to reventer program, if an | drill or deepen directiona | proposal is to deepen or p lly, give pertinent data o | olug back, give data on pr n subsurface locations an | esent pro | ductive some and proposed ed and true vertical depths | new productive. Give blowou |
| 4. | , | | | | | |
| RIGNED | forma | TITLE | Area Manager | | Decemb | er 27, 19 |
| | .Stuart ral or State office use) | | | | | |
| PERMIT NO. | - La Court Court Corry | | APPROVAL DATE | | | |
| | | | | | | |

| | 0'FSL 960'FEL | round | | |
|-------------|----------------|-------|----------|--|
| | | • | | |
| | | | <u> </u> | |
| | Sec. | | | |
| · · · | | 13 | 960' | |
| | | | 1700, | |
| | i | | \ | |
| CALE—4 INCH | ES EQUALS 1 MI | LE | | |

RATHERFORD UNIT #13-43

Supplement to Form 9-331C "Application for Permit to Drill, Deepen, or Plug Back."

DRILLING PROGRAM

 Surface formation is the Dune Sand, which consists of loose windblown sand, age-recent.

Estimated tops of geologic markers:

| Shinarump | • | • | • | • | • | • | • | • | • | • | | • | | 2161 |
|------------|---|---|---|---|---|---|---|---|---|---|---|---|--|------|
| DeChelly | • | • | • | • | • | • | | • | • | • | • | | | 2496 |
| Hermosa | | | | | | | | | | | | | | |
| Desert Cre | | | | | | | | | | | | | | |

- 2. Brackish water-bearing sands are expected in the Navajo, Wingate, and DeChelly formations. Oil is expected to be encountered in the Ismay and Desert Creek formations. The top of cement will be approximately at 2000'.
- 3. Blow-out preventers will be 10" Series 900 equipment to be tested initially to 3000 psi. They will be inspected and operated daily and pressure tested weekly to 1500 psi. Weekly pressure tests will be supervised by representatives of Phillips Oil Company and the drilling contractor. Tests will be recorded on the daily drilling report which will remain on the rig floor during drilling operations. BOP tests will be conducted in accordance with Phillips standards, copy attached.
- a. Proposed Casing Program:
 - 1. Conductor casing:

100' 13-3/8" 48#/ft H-40 ST&C new

2. Surface casing:

1600' 9-5/8" 36#/ft K-55 ST&C new Surface casing will be tested to 1500# before drilling out.

3. Production casing:

5700' 7" 23# & 26#/ft K-55 ST&C new Production casing will be tested to 3000#.

b. Proposed Cementing Program:

1. Conductor Casing:

Conductor casing will be cemented with 150 sks Class B cement. Cement will be brought to surface.

2. Surface Casing:

Surface casing will be cemented with 300 sks "light" cement followed with 300 sks Class B cement. Cement will be brought to surface.

3. Production casing:

Production casing will be cemented with "light" cement followed with Class B cement. For cement volume, caliper will be used with 15% excess. The top of the cement should be around 2000'. If other zones with hydrocarbon potential are encountered, they will be covered with cement.

c. Auxiliary Equipment:

Auxiliary equipment will include upper and lower kelly cocks, a drill string safety valve, and a pit level indicator.

5. Drilling Fluid:

Drilling fluid will be a fresh water based mud system. Spud mud is gel and water with a weight of 8.4-8.8 ppg. From the surface to approximately 1600', gel and water will be used. Mud weight may be up to 9 ppg to control water flow from the Wingate formation. A slurry of 8.6-9.5 ppg, 32-38 viscosity, and less than 15cc/30 min. water loss will be used from 1600'-5200'. Mud weight may be increased to 10.4 ppg if a water flow is encountered. From 5200' to total depth mud properties will be 10.5-12.5 ppg, 40-45 viscosity, and below 10 cc water loss.

Adequate quantities of mud materials will be stored at the location to equal the volume of the rigs complete circulating system. A flow sensor will be used.

6. Testing, logging, and coring:

The logging program will consist of DLL, GR, SP, and Caliper from T. D. to the surface casing. A FDC/CNL and a Micro-proximity log will be run from T. D. to 4300'. A temperature or cement bond log will be run to determine cement top. It is proposed to core the Desert Creek Zone I.

7. Downhole Conditions:

Drilling in the area indicates no abnormal pressures, temperatures, or hydrogen sulfide gas.

8. Phillips anticipates starting operations in the first quarter of 1985. Drilling operations are estimated to take fifteen days per well.

CULTURAL RESOURCE REPORT

Abajo Archaeology has prepared a cultural resource inventory of the subject wellsite. A copy of the report has been sent to the BLM Farmington office. Pertinent information regarding the subject well is attached.

SURFACE USE PROGRAM

- 1. Existing Roads
 - a. Access to existing lease roads is approximately 3 miles southeast of Montezuma Creek, Utah.
 - b. The existing roads will be maintained in the same or better condition.
 - c. Refer to the attached access road map for road information.
- 2. Access Roads

Planned upgrading of existing access roads is shown on the attached map.

3. Location of Existing Wells.

Locations of existing wells are shown on the attached maps.

4. Production from the proposed well will be piped to Ratherford Unit Tank Battery #2, located in the NW SE Sec. 12-T41S-R23E San Juan County, Utah. The flowline will be visible from the existing lease roads. A plat of the proposed leadline is attached.

5. Water Supply

- a. The source of water to drill the subject well is from the River Booster, NE/4 Sec. 5., or from the Water Injection Plant, SE/4 Sec. 17 in T41S-R24E, San Juan County, Utah.
- b. The drilling water will be trucked from the water source to the subject well.
- c. A water supply well will not be drilled on the lease.

6. Construction Materials

a. Only native soils will be used for construction of wellsite and the access road.

- b. Pit run rock will be used on the wellsite and access road when needed.
- c. The above materials are owned by the Navajo Tribe.

7. Waste Disposal

- a. Cuttings: Cuttings will be contained in a fenced reserve pit until dry enough to cover. Upon abandonment, the reserve pit area will be backfilled, shaped to natural topography, and seeded.
- b. Drilling Fluid: Drilling fluid will be contained in a fenced reserve pit until dry enough to cover. Upon abandonment, the reserve pit area will be backfilled, shaped to natural topography, and seeded.
- c. Garbage/Trash: All garbage and trash will be put in the burn pit. The burn pit will be fenced on four sides. After the burn pit is no longer in use, the trash and garbage will be covered with a minimum of 4 feet of fill.
- d. Salt: No salts are anticipated on this well. If salt is present, it will be disposed of in the reserve pit.
- e. Chemicals: Chemicals will be disposed of in the reserve pit.
- f. Sewage: Dry chemical toilets will be used.
- Ancillary Facilities

No ancillary facilities are required.

- 9. Well Site Layout.
 - a. Refer to attached Rig Layout plat
 - b. There are no plans to line the reserve pit unless porous soil materials are encountered during construction.

10. Surface Reclamation Plans

- a. Construction Program: A cross section of the drill site showing cuts and fills is attached.
- b. Well Abandonment: All disturbed areas will be shaped to the natural topography and seeded in accordance with BLM requirements.
- c. Producing Well: Those areas not needed for production purposes will be recontoured to the surrounding topography. Seeding will be in accordance with BLM requirements.

- d. Pipelines and flowlines: Flowlines will be above ground and follow or be visable from existing roads.
- e. Rehabilitation will begin as soon as possible, considering weather and other factors, and proceed per recommendation of the BLM. The reserve pit will be reclaimed once it dries.
- 11. Surface Ownership: The wellsite location, access road and leadline are on the Navajo Indian Reservation. No dwellings are in the proposed drilling area.
- 12. Other information:

The reserve pit will be fenced on three sides during drilling and on the fourth side after the rig is moved out.

- 13. Operator's Representative and Certification.
 - a. Field Representative:


A. E. Stuart
P. O. Box 2920
Casper, Wyoming 82602
307-237-3791


I hereby certify that I or persons under my direct supervision have inspected the proposed drill site and access route; and I am familiar with the conditions which currently exist; that the statements made in this plan are to the best of my knowledge true and correct; and that the work associated with operations proposed herein will be performed by Phillips Oil Company and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved. This statement is subject to the provisions of the 18 U.S.C. 1001 for the filing of a false statement.


Date <u>Mccomber</u> 28, 1984

A. E. Stuart Area Manager

BJM/fb:1t(18) Casper - RC









DRILLING RIG LAYOUT


5. CAT WALK & PIPE RACKS


6. TRAILERS


OUTLINE OF LOCATION - APPROXIMATELY 300' × 350'
NOT TO SCALE











- 1. BELL NIPPLE 2. FLOW LINE

- 3. FILL-UP LINE 4. 2" FE PRESSURE-OPERATED CHOKE LINE
- VALVE
- 2" FE GATE VALVE 2" FE CHOKE LINE TO MANIFOLD
- 7. 2" FE GATE VALVES
- 8. 2" FE KILL LIME 10. 2" SE OR FE GATE VALVE WITH NEEDLE VALVE
- 11. CASING HEAD HOUSING

Figure 7-10. Standard Hydraulic Blowout Preventer Assembly (2 M or 3 M Working Pressure) Alternative 3 (without Drilling Spool)

Well Control 4 January/83

PHILLIPS PETROLEUM COMPANY

Page 251 Section II

SIELD PRACTICES AND STANDARDS

7.6 Testing Surface Blowout Preventer Equipment

7.6.1 Pressure Test Frequency

All rams, annulars, valves, choke and kill lines, choke manifold, kelly cocks, and safety valves shall be pressure tested at the following frequencies:

- (1) Initial installation of blowout preventers.
- (2) After setting casing, before drilling cement.
- (3) Every 7 days or on first trip out of hole after 7 days since previous pressure test.
- (4) After any component of the blowout preventer assembly is disturbed, replaced or repaired (this includes lines, valves, or choke manifold). In this case, the component changed may be the only component tested.
- (5) Prior to conducting first drill stem test in a series of one or more DST's.
- (6) Any time the Phillips Wellsite Supervisor deems necessary, such as prior to drilling into suspected high pressure zones.



7.6.2 Function Test Frequency

All rams, annulars, valves, and other items specified below, shall be function tested at the following frequencies.

- (1) On initial installation from driller control and remote panel.
- (2) Each trip out of hole alternating between driller's and remote control panel but not more than once every twenty-four (24) hours. Close pipe rams or annular preventer CNLY on drill pipe.

7.6.3 Test Pressures

Use the following table to identify which test is appropriate and at what pressure.

| TEST | DESCRIPTION |
|-------------------------|--|
| Low Pressure | Test to 200-300 psi prior to each high pressure test. |
| Initial Installation | Test all rams, annulars, valves, choke manifold, kelly cocks, and safety valves to the lesser of the following pressures. |
| | . Rated working pressure of the component in the blowout preventer assembly with the exception of annular preventer which is to be tested to 70% of the rated working pressure. |
| · | . The API rated casing burst pressure of the last casing to be utilized in the well with the BOP assembly being tested. |
| · | . Rated working pressure of the casing head. |
| | . If "Cup Tester" is used do not exceed 80% of the API rated burst pressure of the casing. |
| Repair | Repaired or replaced components are to be tested to the same pressures used in the Initial Test. |

JELD PRACTICES AND STANDARDS

7.6.3, cont'd

| TEST | DESCRIPTION |
|------------------------------------|---|
| Weekly and After Setting Casing | Test all rams, annulars, valves, choke and kill lines, choke manifold, kelly cocks, and safety valves, to the lesser of the following pressures. |
| | . 50% of the rated working pressure of the component to be tested. |
| | . 80% of the API rating of the casing burst pressure then in the well. |
| · | . Test blind rams during internal casing pressure test. (Refer to drilling program for test pressures). |
| DST Operations | Test all pipe rams, annular preventers, valves, choke and kill lines, choke manifold, kelly cocks, and safety valves to the maximum anticipated surface pressure expected while conducting drill stem tests. Do not test annular to more than 70% of its working pressure. |
| Shallow Casing | Where cased hole is less than 2000 feet measured depth, the test pressure may be 1.5 psi per foot of casing depth, not to exceed 80% of the API rated burst pressure. In the case of shallow conductor casing or drive pipe (500 feet or less) that is equipped with one BOP, then the test pressures do not need to exceed 1.0 psi per foot of casing depth. |
| Accumulator | Test accumulator to the manufacturer's rated working pressure. Test the accumulator for time to pump up to specifications. |

7.6.4 Blowout Preventer Test Practices

(1) All pressure tests shall be witnessed by Phillips' Representative and the Contractor's Senior Supervisor on Location. All tests shall be recorded on the Phillips' Daily Drilling Report, the IADC Report and the BOP Test Form; see Figure 7-13. A reproducible copy of the BOP Test Form (Figure 7-13) can be found in Section III.

Well Control 4

FIELD PRACTICES AND STANDARDS

7.6.4, cont'd

- (2) Hold all low pressure tests for three minutes and high pressure tests for five minutes or until Phillips Representative and the Contractor's Senior Supervisor are satisfied no leaks exist.
- (3) A detail procedure for the testing of blowout preventer and choke manifold equipment will be included in the drilling programs. The procedure is to be distributed for each drilling unit under contract by the operating office. Each operating office must include the following practices:
- a. Prior to testing, all lines and valves will be thoroughly flushed to ensure the system is clear. Test all opening and closing control lines to 1500 psi and inspect for leaks.
- b. If necessary, run a stand of drill collars below the test plug to prevent unseating the test tool during testing.
- c. All precautions must be taken to avoid pressuring the casing below the test tool.
- d. The running string is to be full of water (or antifreeze solution) for immediate indication of test tool leakage.
- e. All pipe rams, blind/shear rams, blind rams, annular preventers, valves, fail-safe valves, choke and kill lines are to be tested at the frequencies and pressures outlined in this section.
- f. Drill pipe safety valve, lower and upper kelly cocks are to be tested from below at pressures and frequencies outlined in this section.
- g. All test fluids are to be bled back to the pump unit in safe manner.

7.6.5 Testing Wellhead Pack-offs

The wellhead pack-off is to be pressure tested upon installation for five minutes. Test pressure is to be 80% API rated casing collapse or the rated working pressure of the casing head whichever is the lesser. Casing annulus valve(s) must be in open position to prevent casing collapse during pack-off testing.

When testing the wellhead pack-off, use recorded test pressures and volumes to determine if pack-off is leaking. Pressure should be immediately released at the first indication of a leak.



7.6.6 Safety Precautions

One pumping unit operator is to be stationed at the high pressure pumping unit, and is to remain at this station until all testing has been completed. The pump unit operator is to be in continuous communication with the person who is recording the test data. The Phillips Wellsite Supervisor and Contractor's Senior Supervisor on location will be the only personnel who will go into the test area to inspect for leaks when the equipment involved is under pressure. The rig crews are to stay clear of the area until such time that both the Phillips Wellsite Supervisor and the Contractor's Senior Supervisor have contacted the pumping unit operator and all three have agreed that all pressure has been released, and there is no possibility of pressure being trapped. The rig crews may then go into the area to repair leaks or work as directed.

All lines, swings, and connections that are used in the testing of the blowout preventers are to be adequately secured in place.

Pressure is to be released only through the pressure release lines that are vented back into the pump unit tanks. The lines are to be clamped down to direct the flow into unit tanks.

ARCHAEOLOGICAL SURVEYS OF 13 PROPOSED WELL LOCATIONS, THEIR ASSOCIATED ACCESS ROADS AND FLOW LINE ROUTES, AND 9 MILES OF PROPOSED WATER INJECTION LINE ROUTES IN SAN JUAN COUNTY, SOUTHEASTERN UTAH

| 12-W24 | 13-12 | 13-43 |
|----------------|-------|--------|
| 12-34 | 13-14 | 18-W12 |
| | 13-21 | 24-41 |
| 14-41 13-11 | 13-23 | 29-22 |
| 13-17 | 13-34 | |

Water Injection Lines: Mainline and Lines A, B, C, D, E, F, F-1, G, H, I, and J

Prepared by:

Debra Foldi Archaeological Consultant

Prepared for:

Phillips Oil Company Cortez, Colorado

Submitted by:

William E. Davis, Director Abajo Archaeology Bluff, Utah

August 1984

Navajo Nation Antiquities Permit No. 1984-24
United States Department of the Interior
Bureau of Indian Affairs
Branch of Environmental Quality Control Authorization
BIA-NAO-84-ABA-048-1
and

Utah State Permit No. U-84-8-5-i

TABLE OF CONTENTS

| ABSTRACTiv |
|-------------------------------|
| INTRODUCTION 1 |
| DESCRIPTION OF PROJECT AREA 6 |
| CULTURE HISTORY 7 |
| METHODOLOGY8 |
| RESULTS14 |
| RECOMMENDATIONS22 |
| REFERENCES CITED23 |
| APPENDIX: Site form SJC-1106 |

LIST OF FIGURES

| FIGURE | 1 | | | | | | | | | 2 |
|-------------|--------|-------|---------|---------|---------|-----------|-------------|-----------|-------------|------------|
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| FIGURE | 5 | | • • • • | | • • • • | | | • • • • • | | 18 |
| FIGURE | 6 | • • • | • • • • | | | | • • • • • • | | • • • • • • | 19 |
| FIGURE | 7 | | • • • • | | | • • • • • | | • • • • • | | 20 |
| FIGURE | 8 | | | | | | ••,•••• | •••• | | 21 |
| | | | | | | | | | | - . |
| | | | | | | | | | . • , | |
| • | | | | | | | | | • | |
| | | | | | | | TABLES | | | |
| | | | | | | | | | | |
| TABLE | 1 | ••• | | • • • • | • • • • | • • • • • | ••••• | | | |
| TABLE | 1 | ••• | | • • • • | • • • • | • • • • • | ••••• | | ••••• | |
| TABLE TABLE | 1 2 | ••• | • • • | • • • • | • • • • | | | | 11 | . 4 |
| TABLE TABLE | 1 2 | ••• | • • • | • • • • | • • • • | | | | • • • • • • | . 4 |

ABSTRACT

Cultural resource surveys were conducted as part of the Rutherford Unit expansion project for Phillips Oil Company, in southeastern San Juan County, Utah. The surveys were performed on August 4, 6, 7, 9, and 11, 1984 on 13 proposed well location sites, eight associated access roads, portions of six associated flow line routes, and along nine miles of proposed injection line. The project area occurs in Sections 11, 12, 13, 14, and 24 in T 41 S, R 23 E and Sections 7, 17, and 18 in T 41 S, R 24 E, USGS White Mesa Village Quadrangle, Utah, 15'. It is under jurisdiction of the Bureau of Indian Affairs.

Seventeen isolated finds and one Anasazi Basketmeker II to Pueblo I artifact scatter (SJC-1106) were located during the survey. The isolated finds are not considered significant in terms of the eligibility criteria set forth in the National Register of Historic Places, thus, archaeological clearance is recommended for the project area, except the 100 meters of mainline injection pipeline east of its juncture with line J. It is recommended that the pipeline be rerouted or that an archaeologist be present to monitor construction of that portion of pipeline.

INTRODUCTION

On August 4, 6, 7, 9, and 11, 1984, cultural resource surveys were conducted within the Rutherford Unit south of Montezuma Creek, southeast San Juan County, Utah (Figure 1). The surveys were requested by Mr. Max Issacs, supervisor of Phillips Oil Company of Cortez, Colorado, and carried out at the request of Mr. Bob Hogg, engineer, and Mr. John White, who replaced Mr. Max Issacs. Both Mr. Hogg and Mr. White were present in the field during portions of the survey. Mr. Hogg assisted the archaeologist by flagging the access routes and flow lines during the survey. The project consisted of 13 proposed well locations, their associated access routes and flow lines, and approximately nine miles of proposed injection pipeline.

The project area lies within the boundaries of the Navajo Reservation (Tables 1 and 2) which is under the jurisdiction of the United States Department of the Interior, Bureau of Indian Affairs and the Navajo Nation. Cultural resources are administered by the USDI-BIA, Branch of Environmental Quality and by the Navajo Nation Cultural Resource Management Program.

The purpose of the survey was to verify the presence of and document any cultural resources within the proposed project impact areas. The accomplishment of these objectives fulfills compliance requirements for the preservation of archaeological and historical resources set forth by the American Antiquities Act of 1906, the Historic Preservation Act of 1966, the National Environmental Policy Act of 1969, Executive Order No. 11593 of 1971, the Archaeological and Historical Conservation Act of 1974, and the Archaeological Resources Protection Act of 1979. Cultural resources occurring on Navajo Tribal lands are further protected by Tribal laws: CJA-16-72 of 1972, Res. ACAP-86-77 of 1977, and the Navajo Tribal Code, Title Nineteen, Sections 1002 and 1004.

Field work was conducted under the Navajo Nation Antiquities Permit No 1984-24, the USDI-BIA, Environmental Quality Authorizaion No. BIA-NAO-84-048-1, and State of Utah Permit No. U-84-8-5-i. These permits and authorizations were granted to Abajo Archaeology of Bluff, Utah. BIA-NAO-84-ABA-048-1 is a "non-collection, non-disturbance" use authorization to conduct archaeological surveys on Navajo Tribal lands. The surveys were performed by Debra Foldi, an archaeological consultant with Abajo Archaeology. Dr. Anthony Klesert, Director of the Navajo Nation Cultural Resource Management Program and Mr. Terry




Figure 1. Location of Phillips Oil Company Rutherford Unit - 1984 expansion project. Stippling outlines project area.

Map Scale: 1:62,5000

TABLE 1 Legal Description of Project Area

Jurisdiction: Navajo Nation
Map: White Mesa Village Quadrangle, Utah, 1962, 15'

| Well Pad | Legal Location | UTM (Zone 12) | Access Route, Length |
|----------|----------------|----------------|-----------------------|
| 10 **0/ | OTOTOL Con 12 | 647,000 m E | 300 feet (runs west |
| 12-W24 | CTSESW, Sec.12 | 4,121,825 m N | from location) |
| | T 41 S, R 23 E | 647,700 m E | 600 feet (runs SSW |
| 12-34 | SESWSE, Sec.12 | 4,121,800 m N | from location) |
| | T 41 S, R 23 E | 646,250 m E | 1000 feet (runs west |
| 14-41 | NENENE, Sec.14 | 4,121,950 m N | from location)-flow |
| | T 41 S, R 23 E | 4,121,930 m N | line follows access |
| | | 616 600 - F | 800 feet (runs north |
| 13-11 | CINWNW, Sec.13 | 646,600 m E | from location)-flow |
| | T 41 S, R 23 E | 4,121,950 m N | line follows access |
| | | | 1300 feet (runs west |
| 13-12 | NWSWNW, Sec.13 | 646,600 m E | from location)-flow |
| • • | T 41 S, R 23 E | 4,121,075 m N | line follows access |
| | | | |
| 13-14 | CTSWSW, Sec.13 | 646,600 m E | 800 feet (runs WSW |
| | T 41 S, R 23 E | 4,120,175 m N | from location) |
| 13-21 | CTNENW, Sec.13 | 647,000 m E | No access surveyed |
| | T 41 S, R 23 E | 4,121,400 m N | No flow line surveyed |
| 13-23 | CTNWSW, Sec.13 | 647,000 m E | No access surveyed |
| | T 41 S, R 23 E | 4,120,600 m N | No flow line surveyed |
| 13-34 | CTSWSE, Sec.13 | 647,700 m E | 600 feet (runs south |
| 20 0 | T 41 S, R 23 E | 4,120,200 m N | from location)-flow |
| | | | line follows access |
| 13-43 | SWNESE, Sec.13 | 647,750 m E | 600 feet (runs NNE |
| 13-43 | T 41 S, R 23 E | 4.120,500 m N | from location)-flow |
| | 1 12 0, 12 2 | • | line follows access |
| 18-W12 | CTSWNW, Sec.18 | 648,225 m E | 500 feet (runs ENE |
| 10-M12 | T 41 S, R 24 E | 4,120,300 m N | from location)-flow |
| | 1 42 0, 2 0 0 | | line follows access |
| 24-41 | CTNENE, Sec.24 | 647,825 m E | No access surveyed |
| 24-41 | T 41 S, R 23 E | 4,119,800 m N | No flow line surveyed |
| 20. 22 | SWSENW, Sec.29 | 650,080 m E | 900 feet (runs east |
| 29-22 | T 41 S, R 24 E | 4,117,600 m N | from location)-flow |
| | 1 41 3, 8 27 5 | .,, | line follows access |
| | | | |

TABLE 2

Legal Descriptions of Water Injection Lines

Jurisdiction: Navajo Nation

Map: USGS White Mesa Village Quadrangle, Utah, 1962, 15'

| Line | Legal Location | Length (Ft.) |
|------|--|--------------|
| Main | SE & SW of SE, SE & SW of SW, Sec.17, T41S, R24E SE & SW of SE, SE & SW of SW, Sec.18, T41S, R24E SE & NW of SE, SE & NW of NW, Sec.13, T41S, R23E SE of SE, Sec.11, T41S, R23E | 18,500 |
| A | SE & NE of SE, Sec.17, T41S, R24E | 1,250 |
| В | Eastern portion of: SE & NE of SE and SE & NE of NE and NENW of NE, Sec.18, T41S, R24E | 6,900 |
| C | SE & NE of SW, Sec.18, T41S, R24E | 1,400 |
| D | SW & NW of SW, SW of NW, Sec.18, T41S, R24E SE of NE, Sec.13, T41S, R23E | 3,250 |
| E | SE of NW, NW & NE of NE, Sec.13, T41S, R23E SE of SE, Sec.12, T41S, R23E SW of SW, Sec. 7, T41S, R24E | 5,500 |
| F | NW of NW, Sec.13, T41S, R23E SE of SW and NW of SE, Sec.12, T41S, R23E | 3,850 |
| F-1 | SE of SW and SW of SW and NW of SW, Sec.12, T41S, R23E | 1,500 |
| G | NW of NW, Sec.13, T41S, R23E/SE of NE, Sec.14, T41S, R23E | 1,700 |
| H | SE of NW and NW of SW, Sec.13, T41S, R23E | 1,500 |
| I | NE of SE and SE of SW, Sec.13, T41S, R23E | 1,700 |
| J | SW of SW, Sec.18, T41S, R24E | 300 |

Del Benee of the USDI-BIA Branch of Environmental Quality were notified prior to performance of the field surveys.

DESCRIPTION OF THE PROJECT AREA

The Phillips Oil Company, Rutherford Unit development project is located in the extreme southeastern portion of San Juan County, just south of Montezuma Creek, Utah. The San Juan River flows to the north (2.5 miles), White Mesa Mountain is to the south, and Flat Top Mountain is situated within the project area. The Rutherford Unit project is within the Blanding Basin of the Colorado Plateau Physiographic Province (Stokes 1977) and is characterized by broken topography ranging in elevation from 4580 feet to 6000 feet above sea level. Most of the project area is flat to rolling terrain, broken by steep-sided mesas, and dissected by intermittent washes and arroyos which feed the San Juan River. The San Juan River is the nearest permanent water source.

The surface geology is reflected in the general The lower flatlands broken nature of the landscape. are fluvial sandstones and mudstones of the Recapture Creek member of the Morrison Formation, which is generally covered by wind blown silts and sands with patches of soil and alluvium (Hintze and Stokes 1964). The lower, light-colored Bluff Sandstone Formation is exposed along Desert Creek (at the east edge of the project area) and portions of Blue Hogan Wash (Hintze and Stokes 1964). The mesas are comprised of the Westwater Canyon and Brushy Basin Members of the Morrison Formation; the later is a dinosaur-bearing, fluvial and lacustrine mudstone and siltstone (Hintze and Stokes 1964) which often contains chert deposits. The coal-bearing sandstone and carbonaceous shales of the Dakota Sandstone cap the higher mesa tops.

The vegetation is in the cool desert climates classified as the Upper Sonoran Life Zone and is characterized by a shadscale (salt desert shrub) plant community. The vegetation noted during the survey included snakeweed, rabbitbrush, shadscale, Mormon tea, big sagebrush, greasewood, saltbush, narrow-leaf yucca, prickly pear cactus, galleta grass, Indian rice grass, cheat grass, locoweed, and Russian thistle. Today, the project area supports a fairly large population of domesticated grazers: sheep, horses, and cattle. Non-domesticates noted during the survey were rabbits, rodents, lizards, and unidentified birds.

- 1

CULTURE HISTORY

Broad overviews have been written, synthesizing the known culture history of southeastern Utah (see Nickens 1982, Weber 1982) and of northwestern New Mexico (see Stuart and Gauthier 1981). In general, the San Juan Basin, as was much of the Colorado Plateau, was inhabited prehistorically by the Basketmakers and Anasazi, relatively sedentary people who first incorporated horticulture into a hunting and gathering subsistence strategy, and later practiced agriculture. The Archaic huntergatherers and the earlier Paleo-Indian, mega-fauna hunters preceded the Basketmakers and Anasazi.

Historically the San Juan Basin, as was much of the Intermountain West, was inhabited by the Navajo and Ute. Although their entry into this area is as little understood as their early history, it is believed that their arrival barely preceded the Spanish Entrada during the 16th century (Wilcox 1981). From that time on, the area was visited by the Spanish, Anglo explorers, trappers, and traders, and later in the 19th century, by the Mormon settlers. Presently, much of the San Juan Basin, primarily the southern portion, is inhabited by the Navajo.

Archaeological surveys related to energy development to the east and northeast of the Rutherford Unit project (see Hewett et al 1979, Moore 1983, 1984, Swift 1984a, 1984b) have documented a variety of sites from artifact scatters to multiroom structures. Documented sites range from the Anasazi Pueblo I phase through recent Navajo. The highest site density occurs during the Anasazi Pueblo II phase, AD 900-1100. In the immediate project area, numerous isolated finds and Basketmaker II through Pueblo III and recent Navajo sites have been recorded (see Langenfeld and Hooten 1984, Langenfeld 1984).

METHODOLOGY

A total of 13 proposed well location sites and eight access routes were inventoried, along with portions of six flow line routes (above ground pipes). A total of 9.13 miles (48,200 feet) of proposed water injection line (buried pipeline) were also inventoried (Figures 2 and 3). Tables 3 and 4 describe the area surveyed. Each of the well location sites were staked prior to the survey, demarcating the 300 by 350 foot pad site. Each well location was inspected by walking parallel transects spaced 10 meters apart back and forth until the entire location was surveyed. An additional 100 foot (30 meter) buffer zone was also inspected around the staked well pad site.

The access roads and flow line routes were flagged while the archaeologist surveyed the well sites. No access routes were surveyed for well locations that were situated on or at the edge of existing maintained roads. Flow lines are to follow proposed and existing roads and existing flow line routes. Only the portions of proposed flow line routes that paralleled proposed access roads which have yet to be built were surveyed. A 100 foot right-of-way was surveyed by walking a zig-zag pattern along each flagged access route. If a flow line was to follow the access route, an additional 25 feet were inspected in the same manner.

The injection line routes were marked by lath stakes. A 50 foot right-of-way was inspected along the staked route, using the stakes as a center line. This was accomplished by walking a zig-zag pattern down one side of the line and back along the other.

All cultural materials encountered during the survey were noted, described, and often illustrated. Those cultural resources which lacked spacial integrity and the potential for interpretable past human behavior (Plog et al 1978) were noted as isolated finds.

In addition to the field inspection, a search of the site files at the Navajo Nation Cultural Resource Management Program in Window Rock, Arizona, was initiated by phone, August 13, 1984. A records search by the Utah Division of State History found no sites to have been previously recorded within the proposed project impact areas.






Figure 2. Locations of proposed well locations, access roads and flow line routes.

Map Scale: 1:62,500




Figure 3. Location and routes of proposed water injection lines.

TABLE 3

Description of Well Pad Project Area and Area Surveyed

| Well Pad | Project Area (square feet) | Area Surveyed (square feet) |
|----------|---|--|
| 12-W24 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access route = 300 ft | 300 ft X 100 ft = 30,000 (0.69 acres) |
| 12-34 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 600 ft | 600 ft X 125 ft = 75,000 (1.72 acres) |
| 14-41 | 300 ft X 350 ft - 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| • | Access & flow line = 1,000 ft | 1,000 ft X 125 ft = 125,000) - (2.87 acres) |
| 13-11 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 800 ft | 800 ft X 125 ft = 100,000 (2.30 acres) |
| 13-12 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 1,300 ft | 1,300 ft X 125 ft = 162,500 (3.73 acres) |
| 13-14 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access route = 800 ft | 800 ft X 125 ft = 100,000 (2.30 acres) |
| | Flow line = 700 ft | 700 ft X 100 ft = 70,000 (1.61 acres) |
| 13-21 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | No access or flow line surveyed | |
| 13-23 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 = 180,000 (4.13 acres) |
| | No access or flow line surveyed | |
| 13-34 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access and flow line = 600 ft | 600 ft X 125 ft = 75,000 (1.72 acres) |

TABLE 3, continued

| Well Pad | Project Area (square feet) | Area Surveyed (square feet) |
|----------|--|---|
| 13-43 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 600 ft | 600 ft X 125 ft = 75,000 (1.72 acres) |
| 18-W12 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 500 ft | 500 ft X 125 ft = 62,500 (1.43 acres) |
| 24-41 | 300 ft X 350 ft = 105,000 (2.41 acres) No access or flow line surveyed | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | NO ACCESS OF LIOW TIME SOLVEYED | |
| 29-22 | 300 ft X 350 ft = 105,000 (2.41 acres) | 400 ft X 450 ft = 180,000 (4.13 acres) |
| | Access & flow line = 900 ft | 900 ft %-125 ft = 112,500 (2.58 acres) |
| | 10 , A waysout 13 | |

Note: The figures for access route and flow line lengths are only for the portions that cross undisturbed areas. Portions that follow maintained roads or existing flow line routes were not surveyed and those figures are not provided here.

TABLE 4

Description of Water Injection Pipeline Project Length and Area Surveyed

| | Desirat Langth | Area Surveyed (square feet) |
|------------------|----------------|---|
| Line | Project Length | ALCO OCCIO/CO (CO |
| Main | 18,500 feet | 18,500 ft X 50 ft = 925,000 (21.23 acres) |
| A | 1,250 feet | $1,250 \text{ ft } \times 50 \text{ ft } = 62,500 \text{ (} 1.43 \text{ acres)}$ |
| В | 6,900 feet | 6,900 ft X 50 ft = 345,000 (7.92 acres) |
| C | 1,400 feet | 1,400 ft X 50 ft = 70,000 (1.61 acres) |
| D | 3,250 feet | 3,250 ft X 50 ft = 162,500 (3.73 acres) |
| E | 5,500 feet | 5,500 ft X 50 ft = 275,000 (6.31 acres) |
| · F | 3,850 feet | 3,850 ft X 50 ft = 192,500 (4.42 acres) |
| F-1 | 1,500 feet | 1,500 ft X 50 ft = 75,000 (1.72 acres) |
| G | 1,700 feet | 1,700 ft X 50 ft = 85,000 (1.95 acres) |
| H | 1,500 feet | 1,500 ft X 50 ft = 75,000 (1.72 acres) |
| I | 1,700 feet | 1,700 ft X 50 ft = 85,000 (1.95 acres) |
| J | 300 feet | 300 ft X 50 ft = 15,000 (0.34 acres) |
| Line rui | | 750 ft X 50 ft = 37,500 (0.86 acres) |
| 24-31 | | |
| Line runeast fro | | Not surveyed, entirely within existing well pad location |

RESULTS

One archaeological site and 17 isolated finds were encountered during the survey. The archaeological site, a Basketmaker II to Pueblo I lithic scatter (SJC-1106) had been previously recorded by San Juan College Cultural Resources Management Program (see appendix for site description). The site had been located during the survey of a proposed access route to Phillips Oil Company's proposed well location \$ 18-24, and relocated during the survey of the Phillips Oil Company proposed injection line pipeline. The site was encountered at the junction of the mainline and line J (Figure 4).

The injection line crosses through the extreme southwest portion of the site, where it has been disturbed by previous pipeline and road construction. Four pieces of lithic debitage were encountered in the pipeline . right-of-way outside of the disturbed area. These artifacts appear to be surficial. Resurvey of the site area found artifact concentrations to occur in the existing roadway and bladed pipeline valve area. Approximately 20 pieces of lithic debitage, one biface, one uniface (chopper), and two unidentified Mesa Verde white ware sherds (7 mm thick with sand temper) were noted during the resurvey. Note: the projectile point fragments The integrity of these deposits were not relocated. has been greatly disturbed by blading activities. Despite the disturbed nature of the site, the potential for buried deposits remains. Also, there is good probability that the site is multicomponent due to the presence of the Archaic diagnostic and the relatively late Puebloan white ware ceramics.

Two alternatives are proposed for this 100 meter section of the pipeline: (1) to build the injection line where proposed with an archaeologist monitoring the construction activities, or (2) to reroute the mainline in order to avoid the site area. This alternative would require an archaeologist to survey the new route.

The remaining cultural materials were isolated finds. A total of 17 isolated finds were encountered during the survey. All are surficial occurrences and are described in Table 5.

GEE ,




Figure 4. Map showing relationship of proposed injection line route and archaeological site - SJC-1106. Site Location: Center of E 1/2, W 1/2, SW 1/2 of Section 18, T 41 S - R 24 E, San Juan County, Utah.

TABLE 5

Isolated Finds from Phillips Oil Rutherford Unit Project Legal Locations and Descriptions

| Number | Legal Location | Description |
|--------|--|--|
| RU # A | CTSESW Sec.12 T41S R23E UTM: 647,000 m E 4,121,825 m N | On location 12-W24. Isolated features: semi-circular, slab feature and two slab piles; a broken cup saucer found insidewhite ovenware, modern; unidentified pipe fragments, wire and sole of shoe. |
| RU # B | CTNENW Sec.13 T41S R23E UTM: 647,000 m E 4,121,400 m N | 13-21. 3 gray-green chert, interior core reduction flakes. |
| RU # C | CTNWNW Sec.13 T41S R23E UTM: 646,600 m E 4,121,950 m N | 13-11. Gray and red quartzite cobble tool; 3 flakes removed. |
| RU # D | CTNWSW Sec.13 T41S R23E UTM: 647,000 m E 4,120,600 m N | *13-23. Biface with crude, heavily weathered flake scars, material type is light and dark gray mottled chert with tan cortex. |
| RU # E | NWSWSE Sec.13 T41S R23E UTM: 647,690 m E 4,120,400 m N | Access road to 13-34. 4 unidentified corrugated sherds; 4 recent Pepsi bottles. |
| RU # F | CTSWSE Sec.13 T41S R23E UTM: 647,700 m E 4,120,200 m N | *13-43. 1 crude olive-green oolitic chert biface. |
| RU # (| UTM: 646,250 m E 4,121,950 m N | |
| RU # 1 | H NENWNW Sec.13 T41S R23E UTM: 646,775 m E 4,121,550 m N | *Injection line 12-24 to 13-11. 1 grainy, tan to yellow chert uniface with heavily weathered, yellowish patina; flake scars are smooth. |
| RU # | I NWNWNE Sec.18 T41S R24 UTM: 648,950 m E 4,121,325 m N | E 18-21 to 18-41. 3 green quartzite interior core reduction flakes. |

TABLE 5, continued

| Number | Legal Location | Description |
|--------|---|---|
| RU # J | NWSESE Sec. 18 T41S R24E UTM: 649,300 m E 4,120,150 m N | 18-44 to 18-34. I gray-tan quartzite, utilized, secondary reduction flake; 1 green quartzite secondary reduction flake. |
| RU # K | NESWSW Sec.18 T41S R24E UTM: 648,450 m E 4,120,175 m N | 18-34 to 18-14. I white quartzite, tertiary reduction flake; I green-gray quartzite, tertiary reduction flake. |
| RU # L | NWSWSE Sec.17 T41S R24E UTM: 650,400 m E 4,120,100 m N | 17-14 to 17-44. 2 white chert, interior core reduction flakes. |
| RU # M | SWNWSW Sec.18 T41S R24E UTM: 648,200 m E 4,120,350 m N | 18-13 to 18-14. 4 gray quartzite, secondary reduction flakes. |
| RU # N | NWSESE Sec.13 T41S R23E UTM: 647,700 m E 4,120,350 m N | ary reduction flake. |
| RU # O | UTM: 647,025 m E 4,121,000 m N | *13-22 to 13-33. 1 green chert uniface with brown patina; 1 tan quartzite, tertiary reduction flake. |
| RU # P | UTM: 647,700 m E 4,121,725 m N | *13-31 to 12-44. 1 green-gray quartzite uniface. |
| RU # Q | NESESE Sec.13 T41S R23E UTM: 647,075 m E 4,121,100 m N | *13-22 to 13-31. 1 gray quartzite uniface with tan to brown patina. |

^{*} illustrated isolated finds.

note: all UTM coordinates are in zone 12.




Figure 5. Flaked Stone Tools




Figure 6. Flaked Stone Tool

Greenish-gray quartzite Uniface IF-P

Figure 7. Flaked Stone Tool




Figure 8. Flaked Stone Tool

RECOMMENDATIONS

SEEATTACHMENT One potentially significant archaeological site was encountered during the survey. As outlined in section "Results", the 100 meters of injection line (the mainline) west of line J can either be constructed as planned or rerouted. If the line is positioned as proposed, an archaeologist should be present to monitor construction of the 100 meters of mainline injection pipeline, extending east from line J. In the event that buried cultural deposits are encountered, construction should stop and the BIA area archaeologist be notified. The other alternative would be to reroute a portion of the mainline in order to avoid the site. An archaeological clearance would be needed if a new route is proposed. ~ New Route HAS BEEN SURVEYED

The remaining cultural resources encountered during the survey were isolated finds which indicate prehistoric and modern use of the area. Most of these are the waste products from flint knapping activities. Several unifacial tools and one biface were also found. Recordation has exhausted the research potential of these isolated finds. Archaeological clearance is recommended for the proposed Rutherford Unit development project well locations, associated access roads and flow lines, and for the proposed injection line routes: mainline and lines A, B, C, D, E, F, F-1, G, H, I, and J, except for the 100 meter of mainline extnding east from its junction with line J.

REFERENCES CITED

- Hewett, Nancy S., Margaret A. Powers, and Meade F. Kemrer
 1979 An Archaeological Survey and Evaluation of
 Cultural Resources Along the San Juan River
 Near Aneth, Utah. Division of Conservation
 Archaeology, San Juan County Archaeological
 Research Center and Library. Farmington,
 New Mexico.
- Hintze, Lehi F. and William Lee Stokes

 1964 Geologic Map of Southeastern Utah. Williams
 and Heintze Map Corporation, Washington D.C.
- Langenfeld, Kristin

 1984 Archaeological Surveys of Six Proposed Well

 Locations and Associated Flow Lines and Access

 Routes in San Juan County, Utah, Conducted

 for Phillips Petroleum Company. Cultural

 Resources Management Program, San Juan College.

 Farmington, New Mexico.
- Langenfeld, Kristin and L. Jean Hooton

 1984 Archaeological Surveys of Thirteen Proposed

 Well Locations and Associated Flow Lines and

 Access Routes in San Juan County, Utah, Conducted
 for Phillips Petroleum. Cultural Resources

 Management Program, San Juan College. Farmington, New Mexico.
- Moore, Roger A.

 1983 An Archaeological Survey of Two Well Locations

 and Access Routes Near Aneth, Utah. Division
 of Conservation Archaeology, San Juan County
 Museum Association. Farmington, New Mexico.
 - An Archaeological Survey of 15 Drill Locations in the White Mesa Unit South of Montezuma Creek in San Juan County, Utah. Division of Conservation Archaeology, San Juan County Museum Association. Farmington, New Mexico.
- Nickens, Paul R.

 1982 "A Summary of the Prehistory of Southeastern
 Utah", IN Contributions to the Prehistory
 of Southeastern Utah. Assembled by Steven
 G. Baker. Centuries Research Inc. Utah State
 Office, Bureau of Land Management, Cultural
 Resource Series, No. 13.

- Plog, Steven, Fred Plog and Walter Wait

 1978 "Decision Making in Modern Surveys", IN Advances
 in Archaeological Method and Theory, Vol.1,
 edited by M.B. Schiffer, pp. 383-421. Academic
 Press, New York.
 - Stokes, William L.
 1977 "Subdivision of the Major Physiographic Provinces
 in Utah". Utah Geology 4(1).
 - Stuart, David E. and Rory P. Gauthier


 1981 Prehistoric New Mexico, Background for Survey.

 Historic Preservation Bureau, Department of Finance and Administration, State Planning Division. Santa Fe.
 - Swift, Marilyn
 1984a An Archaeological Survey of Satellite Area
 A and a Pipeline Easement for Well I-12 in
 the White Mesa Unit, San Juan County, Utah.
 Division of Conservation Archaeology, San
 Juan County Museum Association. Farmington,
 New Mexico.
 - 1984b An Archaeological Survey of Six Pipeline Easements to Wells K-20, K-22, K-24, L-23, M-18, and M-20 in Sections 7, 18, and 19, T41S, R25E, San Juan County, Utah. Division of Conservation Archaeology, San Juan County Museum Association. Farmington, New Mexico.
 - Weber, Kenneth R.

 1980 Cultural Resource Narrative for Class I Cultural Resources Inventory for BLM Lands in South San Juan Couinty, Utah, part 2, "History and Contempory Cultures". Centuries Research, Inc. (Edition for draft only).
 - Wilcox, David R.

 1981 "The Entry of Athapaskans into the American Southwest: the problem today", IN The Protohistoric Period in the North American Southwest, edited by D.R. Wilcox and W.B. Masse. Arizona State University Anthropological Research Papers, No. 24.

| OPERATOR Phillips all WELL NAME Ratherford Wint #13-43 SEC NESE 13 T W/S B 235 COUNT | DATE 1-15-85 |
|--|-----------------------|
| WELL NAME Ratherford Wint # 13-43 | |
| SEC NESE 13 T 415 R 23E COUNT | IV San Juan |
| 43-637-31131 API NUMBER | Julian TYPE OF LEASE |
| CHECK OFF: | |
| PLAT | NEAREST WELL |
| LEASE | POTASH OR OIL SHALE |
| PROCESSING COMMENTS: _ Whit well - R on POD Weel water permit | |
| neel water seemit | |
| | |
| | |
| DDDOVAL A STTED. | |
| PPROVAL LETTER: PACING: A-3 Ratherford C- | -3-a CAUSE NO. & DATE |
| c-3-b | -3 - c |
| TIPULATIONS: | |
| · | |
| | |
| | |
| | |





4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

January 17, 1985

Phillips Oil Company P. C. Box 2920 Casper, Wyoming 82602

Gentlemen:

Re: Well No. Ratherford Unit #13-43 - NE SE Sec. 13, T. 41S, R. 23E 1700' FSL, 960' FEL - San Juan County, Utah

Approval to drill the above referenced oil well is hereby granted in accordance with Section 40-6-18, Utah Code Annotated, as amended 1983; and predicated on Rule A-3, General Rules and Regulations and Rules of Practice and Procedure, subject to the following stipulations:

 Prior to commencement of drilling, receipt by the Division of evidence providing assurance of an adequate and approved supply of water.

In addition, the following actions are necessary to fully comply with this approval:

- Spudding notification to the Division within 24 hours after drilling operations commence.
- Submittal to the Division of completed Form OGC-8-X, Report of Water Encountered During Drilling.
- Prompt notification to the Division should you determine that it is necessary to plug and abandon this well. Notify John R. Baza, Petroleum Engineer, (Office) (801) 538-5340, (Home) 298-7695 or R. J. Firth, Associate Director, (Home) 571-6068.
- Compliance with the requirements and regulations of Rule C-27, Associated Gas Flaring, General Rules and Regulations, Oil and Gas Conservation.

Phillips Oil Company Well No. Ratherford Unit #13-43 January 17, 1985 Page 2

This approval shall expire one (1) year after date of issuance unless substantial and continuous operation is underway or an application for an extension is made prior to the approval expiration date. 5.

The API number assigned to this well is 43-037-31131.

Sincerely,

Associate Director, Oil & Gas

Enclosures cc: Branch of Fluid Minerals Bureau of Indian Affairs

RECEIVED

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

| UNITED STAT | | 5. LEASE |
|--|---|---|
| DEPARTMENT OF THI GEOLOGICAL SU | | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND RE | PORTS ONAWELING | 7. UNIT AGREEMENT NAME |
| Do not use this form for proposals to drill or to eservoir. Use Form 9-331-C for such proposals.) | deepen or plug back to a different | 8. FARM OR LEASE NAME Ratherford Unit |
| 1. oil gas uell other | | 9. WELL NO. #13-43 |
| 2. NAME OF OPERATOR Phillips Petroleum Compan | у | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR 8055 E. Tufts Ave. Pkwy., | Denver, CO 80237 | Greater Aneth 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| 4. LOCATION OF WELL (REPORT LOCAT below.) | TION CLEARLY. See space 17 | Sec. 13-T415-R23E |
| AT SURFACE: 1700' FSL, 960' AT TOP PROD. INTERVAL: | FEL (NE/SE) | 12. COUNTY OR PARISH 13. STATE |
| AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO IND | ICATE NATURE OF NOTICE. | San Juan Utah 14. API NO. 43-037-31131 |
| REPORT, OR OTHER DATA | | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 4645' ung. GL |
| REQUEST FOR APPROVAL TO: SL FEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) | JBSEQUENT REPORT OF: | (NOTE: Report results of multiple completion or zone change on Form 9–330.) |
| including estimated date of starting a measured and true vertical depths for | any proposed work. If well is d all markers and zones pertiner | |
| | (550 sx) Class B Li Pressure tested cas | 26# K-55 ST&C casing, set at 5506'; ight; tailed with 360 cu.ft. (300 sx sing to 2250 psi. Job complete |
| | | |
| · - | | · |
| | | · |
| Subsurface Safety Valve: Manu. and Type | | Set @ Ft. |
| 18. I hereby ceptify that the foregoing is t | rue and correct | |
| SIGNED HELDER WIND | Z TITLE Drilling Mana | ager DATE August 27, 1985 |
| | (This space for Federal or State of | |
| APPROVED BY | | DATE |
| 6-BLM, Farmington, NM 2-Utah O&GCC, SCL | 1-Chevron USA, Inc. 1-Mobil Oil Corp. | • · |
| 1-Casper 1-File (RC) 1-J. Weichrodt | 1-Texaco, Inc. *See Instructions on Reverse 1-Shell Oil Corp. | s Side |

9-331 1973

2-Utah O&GCC, SLC

1-J. Weichbrodt

1-Casper 1-File(RC)

Form Approved. Budget Bureau No. 42-R1424

5. LEASE

UNITED STATES

| DEPARTMENT OF THE INTERIOR | 14-20-603-247 |
|--|--|
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | Navajo 7. UNIT AGREEMENT NAME SW-I-4192 |
| | 8. FARM OR LEASE NAME Ratherford Unit |
| 1. oil gas well other 2. NAME OF OPERATOR DIVISION OF C | 9. WELL NO. #13-43 |
| Phillips Petroleum Company 3. ADDRESS OF OPERATOR | 10. FIELD OR WILDCAT NAME Greater Aneth |
| 8055 E. Tufts Ave. Pkwy., Denver, CO 80237 | 11. SEC., T., R., M., OR BLK. AND SURVEY OF |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) | AREA Sec. 13-T41S-R23F |
| AT SURFACE: 1700' FSL, 960' FEL, (NE/SE) AT TOP PROD. INTERVAL: AT TOTAL DEPTH: | 12. COUNTY OR PARISH 13. STATE San Juan Utah |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. |
| REPORT, OR OTHER DATA | 43-037-31131 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 4645' ung GL |
| TEST WATER SHUT-OFF | (NOTE: Report results of multiple completion or zone change on Form 9–330.) |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen Drilled 18" conductor hole to 122' G.L. on 5-25 BT&C casing. Set at 121.5', cemented with 177 | irectionally drilled, give subsurface locations and t to this work.)* 5-85. Ran 121' 13-3/8" K-55 54.5 cu.ft. (150 sx) Class B cement |
| Spudded well 8-9-85 with Energy Search Drilling to 1600'. Ran 9-5/8" S-80 36# LT&C casing, set 956 cu.ft. (395 sx) Howco Lite cement; tailed we cement. Circulated to surface, fell back; pump Job complete 8-10-85. | g Rig #2. Drilled 12-1/4" hole t at 1600'. Cemented with with 354 cu.ft. (300 sx) Class B |
| Subsurface Safety Valve: Manu. and Type | Set @Ft ger_ DATE _ August 26, 1985 |
| (This space for Federal or State offi | ce use) |
| APPROVED BY TITLE | DATE |
| conditions of approval, if any: 6-BLM, Barmington, NM 1-Chevron USA, Inc. | |

1-Mobil Oil Corp.

1-Shell Oil Co.

1-Texaco, Inc.
*See Instructions on Reverse Side

Form 3160-4 (November 1983) (formerly 9-330)

UP TED STATES SUBMIT DEPARTMENT OF THE INTERIOR

SUBMIT IN DUPL" TE.

(ther instructions on reverse side)

5. LEASE DEBIGNATION AND SERIAL NO

Form approved.
Budget Bureau No. 1004-0137
Expires August 31, 1985

| | | BUREA | AU OF LAND | MANAGEME | NT | | | | | 03-247-A |
|---|----------------------|------------------|---|---|--------------|---------------------|---|-------------|----------------------|---------------------------------|
| WELL CO | API FT | ION O | R RECOM | PLETION F | REPORT | AN | D LOG | * | | LLOTTEE OR TRIBB NAME |
| . TYPE OF WELL | | | | | | | | | Navajo | |
| | | WRLL E | WELL | DRY L | Other | | | | 7. UNIT AGREEM | |
| L TYPE OF COM | LETION: | J DKED- (| — пле (—) | DIFF. | A | | Miles and | _ | SW-I-41 | <u> </u> |
| WELL 🔯 | OVER L | J EN L | T BYCK [] | RENVR. | Other P | | | | | ord Unit |
| . NAME OF OPERAT | | _ | | | | | | | 9. WELL NO. | ord onre |
| Phillips P | | um Comp | oany | | a | OT A | | | 13-43 | |
| . ADDRESS OF UPER | | • | *** | 00600 | | | 287.) | | | POOL, OR WILDCAT |
| P. O. Box | 2920, | Casper, | wyoming | ozouz | u State reau | iremen | ta) • | | Greater | |
| P. O. BOX LOCATION OF WEL At surface 17 | 00' FS | L & 960 | FEL, N | E SE | ID. G | VISIC AS & | ĎŇ Ur U. MINING | | | M., OR BLOCK AND SURVEY |
| At top prod. into | erval repo | rted below | | | | | MILLALIAG | | , G 12 | m/10 D22E |
| At total depth | | | | | | | | | Sec. 13 | -T41S-R23E |
| | | | | 14. PERMIT NO. | | DATE | 188USD | | 12. COUNTY OR PARISH | 13. STATE |
| API #43-03 | 7-3113 | 1 | | | | /~/ | 7-85 | | San Jua | n Utah |
| . DATE SPUDDED | 16. DATE | T.D. REAC | HED 17. DATE | COMPL. (Ready to | 1 | | | | -,,, | 9. BLEV. CASINGHEAD |
| 8/9/85 | 8/ | 24/85 | 9 | /20/85 | ľ | Ing G | R 4645 | , RK | В 4656.5 | |
| . TOTAL DEPTH, MD | | | ACK T.D., MD & T | D 22. IF MUL. | TIPLE COMP | L., | 23. INTER | | ROTARY TOOLS | CABLE TOOLS |
| 5507 ' | | | 5473 ' | HOW M | - A. 1 . | _ | | - 1 | 0 - 5507' | |
| . PRODUCING INTER | VAL(B), O | F THIS CON | | BOTTOM, NAME () | AD AND TVD | • | . <u>. </u> | | | 25. WAS DIRECTIONAL SURVEY MADE |
| | | | | | | | | | | |
| 5424' - 54 | 46' I | esert (| creek Zone | : L | | | | | | No |
| TYPE ELECTRIC A | ND OTHER | LOGA RI'N | · | | | nastronization inco | **** | | 27 | . WAS WELL CORED |
| QSN-CDE, D | 112 G11 | ard Fo | CONTA | ct Caliper |) (B) | ows | | | l | Yes |
| . QUIL GUE, 2 | Contract of the last | | *************************************** | G RECORD (Rep | | an net i | n well) | | | |
| CASING SIZE | WEIGH | IT, LB./FT. | DEPTH SET | | LE SIZE | 1 | | NTING | RECORD | AMOUNT PULLED |
| | - | , , , | 12] | 1 17 | 7-1/2" | 1 | 77 cu. | f+ | Class "B" | |
| 13-3/8" | - | 54.5# | 1600 | | 2-1/4" | | 310 cu. | | <u> </u> | |
| 9-5/8" " | | 36# | 5506 | | 3-3/4" | | 82 cu. | | | |
| | _ 23# | <u>& 26#</u> | _ | <u>, </u> | 5-3/4 | - | 102 Cu. | IL. | CIGSS D | |
| • | <u>'</u> | LIN | ER RECORD | | ··· | | 30. | T | UBING RECORI | |
| . SIZE | TOP (M | 08 (0 | TTOM (MD) | SACES CEMENTS | SCREEN (| MD) | SIZE | 1 | EPTH SET (MD) | PACKER SET (MD) |
| | | | | | | | 2-7/8 | 111 | 5285 | |
| | | | | | | | | | | |
| . PERFORATION REC | ORD (Inte | rval, size e | nd number) | | 82. | AC | ID, SHOT, 1 | FRACT | URE, CEMENT S | QUEEZE, ETC. |
| 5424-5446, | | | | shots | DEPTH I | | 1 | | | OF MATERIAL USED |
| J424-J440, | 2 01.1 | . , . 7 11 | bo oun, . | . Direct | 5424- | | | | | h ft of perfs |
| | | | • | | | | | | | 2226 gal 28% |
| | | | | | | | | | | n inhibitor, |
| | • | | | | | | | | | , 2 gal/1000 F |
| | | | | PRO | DUCTION | | | | | NUED ON BACK) |
| 3.* ATB FIRST PRODUCT | ION: | PRODECT | ON METHOD (FI | owing, gas lift, p | | e and t | upe of pump | ») | | ATUS (Producing or |
| 9/20/85 | | Pumpi | | x 1-1/2 x | | | | • | shut-in | |
| | HOURS | <u> </u> | CHOKE SIZE | PROD'N. FOR | OIL—BBL. | | GAS-MCF | | WATER—BBL. | GAS-OIL RATIO |
| 10/19/85 | носка | | · - SIZE | TEST PERIOD | 27 | • | 11 | | 7 | 400 |
| 10/18/85 | ł | | 0110111455 | OIL—BBL. | | -MCF. | <u> </u> | VATER- | | L GRAVITY-API (CORR.) |
| LOW. TUBING PROCE. | CABING | PRESSURE | CALCULATED 24-HOUR RATE | 27 | | 11 | 1 | 7 | | 40.0 |
| | <u> </u> | | | 1 21 | 1 | | | <u>'</u> | TEST WITNESSE | |
| 4. DISPOSITION OF G | AB (BOIG, | ween jor ju | o, venicu, eic.) | | | | | | | 110 |
| Sold_ | | · | | · · · · · · · · · · · · · · · · · · · | | | | | | - //b \'- |
| 5. LIST OF ATTACH | MENT8 | | | | | | | | | \/\ |
| None | | | · | | | | | | .W | U |
| 6. I hereby certify | that the | foregoing s | ind attached inf | ormation is comp | plete and co | rrect a | s determined | from | an avanable reco | rus |
| | <i>[][</i> | 111 | | | A | Mono | 000 r | | | ctober 23, 198 |
| SIGNED | | | | _ TITLE | Area | riana | iger | | DATE \(\square \) | CLODEL 23, 190 |

Mobil Oil Corporation

P.O. BOX 5444 DENVER, COLORADO 80217-5444

May 14, 1986

Utah Board of Oil, Gas and Mining 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203

Attn: R. J. Firth

Associate Director



DIVISION OF OIL, GAS & MINING

SUPERIOR OIL COMPANY MERGER

Dear Mr. Firth:

On September 20, 1984, The Superior Oil Company (Superior) became a wholly owned subsidiary of Mobil Corporation. Since January 1, 1985, Mobil Oil Corporation (MOC), another wholly owned subsidiary of Mobil Corporation, has acted as agent for Superior and has operated the Superior-owned properties.

On April 24, 1986, Superior was merged with Mobil Exploration and Producing North America Inc. (MEPNA), which is also a wholly cwned subsidiary of Mobil Corporation. MEPNA is the surviving company of the merger.

This letter is to advise you that all properties held in the name of Superior will now be held in the name of MEPNA; and that these properties will continue to be operated by MOC as agent for MEPNA.

Attached is a listing of all wells and a separate listing of injection-disposal wells, Designation of Agent and an organization chart illustrating the relationships of the various companies. If you have any questions or require additional documentation of this merger, please feel free to contact me at the above address or (303) 298-2577.

Very truly yours,

R. D. Baker

Environmental Regulatory Manager

CNE/rd CNE8661

L'NITED STATES

| FOI | RM 4 | PPR | OVE |) |
|----------|--------|-----|------|-------|
| Budget B | lureau | No | 1004 | -1135 |
| Expires | Septe | mbe | r 30 | 1990 |

| | NT OF THE INTERIOR • | Budget Bureau No. 1004-1135 Expires September 30, 1990 |
|--|--|---|
| DUILLAU VI | LAND MANAGEMENT | 5 Lease Designation and Serial No |
| • | | 14-20-603-247 |
| SUNDRY NOTICES | AND REPORTS ON WELLS | 6 If Indian. Allottee or Tribe Name |
| Do not use this form for proposals to de Use "APPLICATION FC | rill or to deepen-or reentry to a different reservoir. OR PERMIT—" for such proposals | Navajo Tribal |
| SHRMI | TIN TRIPLICATE TO PETERS | 7. If Unit or CA. Agreement Designation |
| | | Ratherford Unit |
| 1. Type of Well Gas | | SW-I-4192 8. Well Name and No. |
| Well Well Other | - 111 27 1990 - 111 27 1990 - 111 27 1990 - 111 27 1990 - 111 27 1990 - 111 27 1990 - 111 27 1990 - 111 27 1990 | Ratherford Unit #13-43 |
| 2. Name of Operator | 302 50. 1000 | 9. API Well No. |
| Phillips Petroleum Company 3. Address and Telephone No. | DIVISION OF | 43-037-31131 |
| P. O. Box 1150, Cortez, CO | (303) 565-34260IL, GAS & MINING | 10. Field and Pool, or Exploratory Area |
| 4 Location of Well (Footage, Sec., T., R., M., or Survey I | Description) | Greater Aneth |
| troot per c ocol per Ne ce | C. 12 T/1C_D22F | 11. County or Parish, State |
| 1700' FSL & 960' FEL, NE SE | , Sec 13-1415-R23E | |
| | | San Juan, Utah |
| CHECK APPROPRIATE BOX | (s) TO INDICATE NATURE OF NOTICE, REPOR | RT, OR OTHER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | |
| Notice of Intent | Abandonment | Change of Plans |
| | Recompletion | New Construction |
| Subsequent Report | Plugging Back | Non-Routine Fracturing |
| | Casing Repair | Water Shut-Off |
| Final Abandonment Notice | Alterna Casing Clean out & a | Conversion to Injection |
| | | f multiple completion on Well Completion or |
| | Recompletion Report at | nd Log form.) |
| 13 Describe Proposed or Completed Operations (Clearly state | Recompletion Report at all pertinent details, and give pertinent dates, including estimated date of starting | nd Log form.) any proposed work. If well is directionally drilled |
| Describe Proposed or Completed Operations (Clearly state give subsurface locations and measured and true vert | Recompletion Report at all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. | nd Log form.) any proposed work. If well is directionally drilled |
| give subsurface locations and measured and true vert | all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.10 | nd Log form.) any proposed work. If well is directionally drilled |
| June 25, 1990 Through June | all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work.19 30, 1990 | any proposed work. If well is directionally drilled |
| June 25, 1990 Through June MT & RII well service unit 6 | all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, N | any proposed work. If well is directionally drilled IU BOP. COOH w/ |
| June 25, 1990 Through June MI & RU well service unit 6 168 its 2-7/8" tbg. GIH w/ | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work 30, 1990 /25/90. COOH w/rods & pump. ND WH, Note that we scraper & clean out well to PBTI | any proposed work. If well is directionally drilled IU BOP. COOH w/ |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo | all pertunent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 6/25/90. COOH w/rods & pump. ND WH, North and Secraper & Clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI | NU BOP. COOH w/ 0 5473'. COOH w/ 1 lines to 3500 psi. 0 15% HCL & MSR 100, |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') | all pertinent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, Note to the secraper & clean out well to PBTI del R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/ | NU BOP. COOH w/ 0 5473'. COOH w/ 1 lines to 3500 psi. 0 15% HCL & MSR 100, 1/2 ppg rock salt. |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP O psi. Swbd well. CO | all pertunent details. and give pertinent dates. including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 (/25/90. COOH w/rods & pump. ND WH, N bit & scraper & clean out well to PBTI del R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/00H w/pkr. TIH w/production string, see | TU BOP. COOH w/ 0 5473'. COOH w/ 1 lines to 3500 psi. 0 15% HCL & MSR 100, 1/2 ppg rock salt. |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, Note to the secretary of the s | TU BOP. COOH w/ 0 5473'. COOH w/ 1 lines to 3500 psi. 0 15% HCL & MSR 100, 1/2 ppg rock salt. |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP O psi. Swbd well. CO | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, Note to the secretary of the s | NU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 1/2 ppg rock salt. et TAC at 5338', 1/2 unit, and returned |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH | all pertunent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, Note to the secretary of the s | NU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 5 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 3/25/90. COOH w/rods & pump. ND WH, Note to the secretary of the s | NU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 5 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note that we have a serious with the serious well to PBTI and R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/00H w/pkr. TIH w/production string, set and pump & rods, RD & MO well served that the served restriction were restricted to the served restriction with the served res | NU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note of the secretary of the s | NU BOP. COOH w/ 0 5473'. COOH w/ 1 lines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 5 MCFGPD BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah O&GCC 1 - P. | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note of the scraper & clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/OOH w/pkr. TIH w/production string, set in Ran pump & rods, RD & MO well served. Ran pump & rods, RD & MO well served. Test Prior to Work - 42 BOPD, 13 Test After Work - 73 BOPD, 18 H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston | NU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah O&GCC 1 - P. 1 - EPA, Denver 1 - Ch | all pertunent details, and give pertunent dates, including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note of the secretary of the s | TU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD W 10 |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah 0&GCC 1 - P. 1 - EPA, Denver 1 - Ch 1 - N. Anstine 1 - Mo | all pertunent details. and give pertunent dates. including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, N bit & scraper & clean out well to PBTI del R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/00H w/pkr. TIH w/production string, set. Ran pump & rods, RD & MO well service. Ran pump & rods, RD & MO well service. Test Prior to Work - 42 BOPD, 13 Test After Work - 73 BOPD, 18 H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston dieftain 1 - PPCo, Cortez, RC | TU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD W 10 |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah 0&GCC 1 - P. 1 - EPA, Denver 1 - Ch 1 - N. Anstine 1 - Mo 1 - V. S. Shaw 1 - Te | all pertunent details. and give pertunent dates. including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 30, 1990 30, 25/90. COOH w/rods & pump. ND WH, N bit & scraper & clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/60H w/pkr. TIH w/production string, set. Ran pump & rods, RD & MO well service. Ran pump & rods, RD & MO well service. Test Prior to Work - 42 BOPD, 13 Test After Work - 73 BOPD, 18 H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston dieftain 1 - PPCo, Cortez, RC obil 0il | AU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 5 MCFGPD BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah 0&GCC 1 - P. 1 - EPA, Denver 1 - Ch 1 - N. Anstine 1 - Mo 1 - V. S. Shaw 1 - Te | all pertunent details. and give pertunent dates. including estimated date of starting tical depths for all markers and zones pertunent to this work. 30, 1990 30, 1990 30, 25/90. COOH w/rods & pump. ND WH, N bit & scraper & clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/60H w/pkr. TIH w/production string, set. Ran pump & rods, RD & MO well service. Ran pump & rods, RD & MO well service. Test Prior to Work - 42 BOPD, 13 Test After Work - 73 BOPD, 18 H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston dieftain 1 - PPCo, Cortez, RC obil 0il | JU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah 0&GCC 1 - P. 1 - EPA, Denver 1 - Ch 1 - N. Anstine 1 - Mo 1 - V. S. Shaw 1 - Te | all pertunent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note that & scraper & clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/OH w/pkr. TIH w/production string, set and a rods, RD & MO well served. Ran pump & rods, RD & MO well served. Ran pump & rods, RD & MO well served. H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston dieftain 1 - PPCo, Cortez, RC obil 0il exaco, Inc. | AU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 5 MCFGPD W 100 BWPD, 8 MCFGPD |
| June 25, 1990 Through June MI & RU well service unit 6 168 jts 2-7/8" tbg. GIH w/ bit & scraper. TIH w/7" mo Acidized perfs (5424-5446') then with 2000 gal 15% HCL ISIP 0 psi. Swbd well. CO SN at 5463'. ND BOP, NU WH well to production 6/30/90. Distribution: 5 - BLM, Farmington 1 - S. 2 - Utah 0&GCC 1 - P. 1 - EPA, Denver 1 - Ch 1 - N. Anstine 1 - Mo 1 - V. S. Shaw 1 - Te | all pertunent details, and give pertinent dates, including estimated date of starting tical depths for all markers and zones pertinent to this work. 30, 1990 7/25/90. COOH w/rods & pump. ND WH, Note that & scraper & clean out well to PBTI odel R-3 pkr and set at 5364'. Tested in two stages with 1000 gal 80/20 DAI & MSR 100, diverted w/500 gal WF-40 w/OH w/pkr. TIH w/production string, set and a rods, RD & MO well served. Ran pump & rods, RD & MO well served. Ran pump & rods, RD & MO well served. H. Oden 1 - Chevron J. Konkel 1 - PPCo, Houston dieftain 1 - PPCo, Cortez, RC obil 0il exaco, Inc. | JU BOP. COOH w/ 0 5473'. COOH w/ 1 ines to 3500 psi. 0 15% HCL & MSR 100, 2 ppg rock salt. et TAC at 5338', Ice unit, and returned BWPD, 8 MCFGPD BWPD, 8 MCFGPD |

MONTHLY OIL AND GAS PRODUCTION REPORT

OPERATOR NAME AND ADDRESS:

P J KONKEL

N0772

AUG 1 6 1993

REPORT PERIOD (MONTH/YEAR)

PHILLIPS PETROLEUM COMPANY 5525 HWY 64 NBU 3004 FARMINGTON NM 87401

DIVISION OF

OIL, GAS & MININGMENDED REPORT [(Highlight Changes)

| Well Name | Producing | Well | Days | | Production Volumes | |
|---------------------------------------|-----------|--------|--------|-----------|--------------------|------------|
| API Number Entity Location | Zone | Status | Oper | OIL(BBL) | GAS(MCF) | WATER(BBL) |
| #21-23 4303713754 06280 415 24E 21 | DSCR | POW | 29 | 1374 | 883 | 58 |
| #3-44 4303715031 06280 418 24E 3 | DSCR | POW | 30 | 111 | 94 | 2905 |
| #3-14 4303715124 06280 415 24E 3 | DSCR | POW | 30 | 67 | 23 | 302 |
| #9-12 4303715126 06280 41S 24E 9 | DSCR | POW | 30 | 112 | 654 | 17363 |
| #9-14 4303715127 06280 415 24E 9 | DSCR | Pow | 30 | 201 | 315 | 423 |
| #28-12 4303715336 06280 41S 24E 28 | PRDX | POW | 29 | 112 | 47 | 2428 |
| #29-12 4303715337 06280 41S 24E 29 | PRDX | POW | 29 | <i>56</i> | 0 | 672 |
| #29-32 4303715339 06280 41S 24E 29 | DSCR | POW | 29 | 1402 | 287 | 2224 |
| #29-34 4303715340 06280 415 24E 29 | DSCR | Pow | 29 | 757 | 48 | 0 |
| #30-32 4303715342 06280 415 24E 30 | DSCR | POW | 29 | 588 | 1049 | 3744 |
| #3-12 4303715620 06280 41S 24E 3 | DSCR | POW | 30 | 268 | 11 | 363 |
| #9-34 4303715711 06280 415 24E 9 | DSCR | POW | 30 | 45 | 46 | 9800 |
| #10-12 4303715712 06280 415 24E 10 | DSCR | POW | 30 | 45 | 23 | 1088 |
| | • | | TOTALS | 5138 | 3480 | 41370 |

Effective July 1, 1993, Phillips Petroleum Company has sold its interest in the COMMENTS:

Ratherford Unit to Mobil Exploration and Producing U.S., Incorporated, P. O. Box

633, Midland, Texas 79702. Mobil assumed operations on July 1, 1993.

I hereby certify that this report is true and complete to the best of my knowledge.

PAT KONKEL

at Konkel

Telephone Number: <u>505</u> 599-3452

| _ | PA | 1 |
|---|------------|---|
| | ΓM | 0 |

| 4 | 12W-44 | 43-037-16405 | 14-20-603-246A | SEC. 12, T41S, R23E | SE/SE 660 FSL; 660 FEL |
|---|---|--|---|---|---|
| - 13- | | 43-037-31543 | 14-20-603-246A | SEC. 12, T41S, R23E | SE/SE 807 FEL; 772 FSL |
| | | | | | |
| | | 43-037-31152 | 14-20-603-247A | SEC. 13, T41S, R23E | NW/NW 500 FNL; 660 FWL |
| u | 13-12 | 43-037-31127 | 14-20-603-247A | SEC. 13, T41S, R23E | SW/NW 1705 FNL; 640 FWL |
| | | 43-037-15851 | 14-20-603-247A | SEC. 13, T41S, R23E | NW/SW 1980 FSL; 4620 FEL |
| | | | | | 660 FSL; 660 FWL |
| | 13-14 | 43-037-31589 | 14-20-603-247A | SEC. 13, T41S, R23E | |
| | 13-21 | 43-037-31128 | 14-20-603-247A | SEC. 13, T41S, R23E | NE/NW 660 FNL; 1920 FWL |
| .1 | 13W-22 | 43-037-15852 | 14-20-603-247A | SEC. 13, T41S, R23E | SE/NW 1988 FNL; 3300 FEL |
| | | | | | |
| - ⊩ | 13-23 | 43-037-31129 | 14-20-603-247A | SEC. 13, T41S, R23E | NE/SW 1980 FSL; 1930 FWL |
| ŀ | 13W-44 - | 43-037-15853 - | 14-20-603-247 | - SEC. 13, T416, R23E | 600 FSL; 3300 FEL |
| , L | 13W-32 | 43-037-16406 | 14-20-603-247A | SEC. 13, T41S, R23E | 1881 FNL; 1979 FEL |
| | | 43-037-15855 | 14-20-603-247A | SEC. 13, T41S, R23E | NW/SE 1970 FSL; 1979 FEL |
| | | | | | |
| 4 | 13W-34 | 43-037-31130 | 14-20-603-247A | SEC. 13, T41S, R23E | SW/SE 660 FSL; 1980 FEL |
| J | 13-41 | 43-037-15856 | 14-20-603-247A | SEC. 13, T41S, R23E | NE/NE 660 FNL; 660 FEL |
| - 1 | | 43-037-15857 | 14-20-603-247A | SEC. 13, T41S, R23E | SE/NE 2139; 585 FEL |
| V | 1344-42 | | | | |
| | | 43-037-31131 | 14-20-603-247A | SEC. 13, T41S, R23E | NE/SE 1700 FSL; 960 FEL |
| 4 | 13W-44 | 43-037-16407 | 14-20-603-247A | SEC. 13, T41S, R23E | SE/SE 635 FSL; 659 FEL |
| | | NA | 14-20-603-4037 | SEC. 11, T41S, R23E | SW/SW 660 FSL; 660 FEL |
| II- | | | | | |
| 4 | 14-32 | 43-037-15858 | 14-20-603-247A | SEC. 14, T41S, R23E | 2130 FNL; 1830 FEL |
| 1 | 14-41 | 43-037-31623 | 14-20-603-247A | SEC. 14, T41S, R23E | NE/NE 521 FEL; 810 FNL |
| | | 43-037-15860 | 14-20-603-247A | SEC. 14, T41S, R23E | SE/NE 1976 FNL; 653 FEL |
| | | | | | 3300 FSL; 4770 FEL |
| | | 43-037-16410 | 14-20-603-247A | SEC. 14, T41S, R23E | |
| 4 | 14-33 | 43-037-15859 | 14-20-603-247 | SEC. 14, T41S, R23E | 2130 FSL; 1830 FEL |
| | 15-12 | 43-037-15715 | 14-20-603-355 | SEC. 15, T41S, R24E | 1820 FNL; 500 FWL |
| 1. | | 43-037-16411 | 14-20-603-355 | SEC. 15, T41S, R24E | 660 FNL; 1820 FWL |
| | | | | | |
| - ⊩ | 15-22 | 43-037-30449 | 14-20-603-355 | SEC. 15, T41S, R24E | SE/NW, 1980 FNL; 2050 FWL |
| J. | 15-32 | 43-037-15717 | 14-20-603-355A | SEC. 15, T41S, R24E | 1980 FNL; 1980 FEL |
| | 15-33 | 43-037-15718 | 14-20-603-355 | SEC. 15, T41S, R24E | NW/SE 1650 FSL; 1980 FEL |
| - ⊪ | | | | | |
| - 11 | 15-41 | 43-037-15719 | 14-20-603-355 | SEC. 15, T41S, R24E | 660 FNL; 660' FEL |
| u | 15-42 | 43-037-3044 🖁 📗 | 14-20-603-355 | SEC. 15, T41S, R24E | SE/NE 2020 FNL; 820 FEL |
| J | 16W-12W | 43-037-15720 | 14-20-603-355 | SEC. 16, T41S, R24E | SW/NW 1880 FNL; 660 FWL |
| | 16-13 | 43-037-31168 | 14-20-603-355 | | 1980 FSL; 660 FWL |
| | | | | | SW/SW 660 FSL; 660 FWL |
| | | 43-037-15721 | 14-20-603-355 | SEC. 16, T41S, R24E | |
| ч | 16W-21 | 43-037-16414 | 14-20- <u>603-355</u> | SEC. 16, T41S, R24E | NE/NW 660 FNL; 1880 FWL |
| 4 | Committee of the contract of t | | | OFO 40 TA40 DOAF | NECON 1000 FCL 1000 FMI |
| u | 16W-23 🖼 | 143-037-15722 | 14-20-603-355 | SEC. 16, T41S, R24E | NE/SW 1980 FSL; 1980 FWL |
| -g | | | | | 1980 FNL; 1980 FEL |
| Y | 16-32 | 43-037-15723 | 14-20-603-355 | SEC. 16, T41S, R24E | 1980 FNL; 1980' FEL |
| ų ų | 16-32 16-34 | 43-037-15723 43-037-15724 | 14-20-603-355 14-20-603-355 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL |
| ب د ن | 16-32 16-34 16-41 | 43-037-15723 43-037-15724 43-037-15725 | 14-20-603-355 14-20-603-355 14-20-603-355 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL |
| ب د ن | 16-32 16-34 16-41 | 43-037-15723 43-037-15724 | 14-20-603-355 14-20-603-355 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL |
| ر د د | 16-32 16-34 16-41 16W-43** | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL |
| UUU | 16-32 16-34 16-41 16W-43* 17-11 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL |
| 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 16-32 16-34 16-41 16W-43*4 17-11 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL |
| 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 16-32 16-34 16-41 16W43** 17-11 17W12** | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 17, T41S, R24E SEC. 17, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL |
| 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 16-32 16-34 16-41 16W43** 17-11 17W12** | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL |
| 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | 16-32 16-34 46-41 16W-43 17-11 17W-12 17-13 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-13 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL |
| | 16-32 16-34 16-41 16W-43W 17-11 17W-12W 17-13 17W-14W 17W-21W | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL |
| | 16-32 16-34 16-41 16W-43W 17-11 17W-12W 17-13 17W-14W 17W-21W 17-22 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL |
| | 16-32 16-34 16-41 16W-43W 17-11 17W-12W 17-13 17W-14W 17W-21W | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-15728 43-037-15729 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-31 17-32 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 43-037-31178 43-037-31178 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-15728 43-037-31178 43-037-31134 43-037-15730 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 43-037-31178 43-037-31178 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 17-34 17-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-31134 43-037-15730 43-037-15730 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 17-34 17-42 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-31134 43-037-15730 43-037-15731 43-037-31177 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 17-41 17-42 17-44 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL 5E/NE 1980; FNL, 660' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-31 17-32 17-33 17-34 17-41 17-42 17-44 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-31134 43-037-15730 43-037-15731 43-037-31177 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL 5E/NE 1980' FSL; 1860' FEL SE/NE 1980; FNL, 660' FEL 660 FSL; 660' FEL NE/SE 1980' FSL; 660' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-21 17-22 17-23 17-32 17-33 17-34 17-34 17-42 17-44 17-44 17-44 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL 5E/NE 1980; FNL, 660' FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-42 17-44 17-43 17-43 17-43 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 43-037-15727 43-037-16416 43-037-1170 43-037-15728 43-037-31178 43-037-31178 43-037-31178 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-16417 43-037-15733 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1860' FEL SE/NE 1980; FNL, 660' FEL 660 FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-31 17-32 17-32 17-34 17-44 17-44 17-44 17-44 17-44 17-43 18-11 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 43-037-31178 43-037-31178 43-037-31178 43-037-31177 43-037-15730 43-037-15731 43-037-15731 43-037-16417 43-037-15733 43-037-15733 43-037-15733 43-037-15733 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-23 17-31 17-32 17-31 17-34 17-42 17-44 17-42 17-44 17-42 17-44 17-42 17-44 17-42 17-44 17-42 17-44 17-42 17-44 17-42 17-44 17-43 18-11 18-12 18-12 18-12 18-12 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-31178 43-037-31178 43-037-31179 43-037-31177 43-037-15731 43-037-15731 43-037-16417 43-037-15733 43-037-16417 43-037-15733 43-037-16418 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 1980' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-31 17-32 17-32 17-34 17-44 17-44 17-44 17-44 17-44 17-43 18-11 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 43-037-31178 43-037-31178 43-037-31178 43-037-31177 43-037-15730 43-037-15731 43-037-15731 43-037-16417 43-037-15733 43-037-15733 43-037-15733 43-037-15733 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-31 17-32 17-32 17-34 17-44 17-44 17-44 17-44 17-43 18-12 18-12 18-22 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-31170 43-037-31178 43-037-31178 43-037-31134 43-037-31134 43-037-31134 43-037-31134 43-037-31134 43-037-31134 43-037-31134 43-037-3133 43-037-3133 43-037-3133 43-037-16417 43-037-16418 43-037-31236 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 1980' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-32 17-32 17-32 17-34 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-43 18-12 18-12 18-12 18-22 18-23 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-15728 43-037-15729 43-037-31134 43-037-31134 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15732 43-037-16417 43-037-15733 43-037-16418 43-037-31236 43-037-30244 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL SE/NE 1980' FSL; 1880' FEL SE/NE 1980' FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-34 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 18-12 18-12 18-12 18-12 18-22 18-23 18-23 18-14 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-15728 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15732 43-037-16417 43-037-15733 43-037-16418 43-037-31236 43-037-30244 43-037-15735 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL, 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL 660 FSL; 660' FEL NE/SE 1980; FNL; 730' FWL NE/SE 1980' FNL; 300' FWL SW/NW 1980' FNL; 560' FWL SW/NW 1980' FNL; 300' FWL SW/NW 2200' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 660' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-32 17-32 17-33 17-34 17-34 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-43 18-12 18-12 18-12 18-21 18-23 18-23 18-23 18-24 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15732 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31236 43-037-30244 43-037-3555 43-037-31079 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 3030' FEL SW/NE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980; FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL SW/NW 1980' FNL; 2210' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-34 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 17-42 18-12 18-12 18-12 18-12 18-22 18-23 18-23 18-14 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-15728 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15732 43-037-16417 43-037-15733 43-037-16418 43-037-31236 43-037-30244 43-037-15735 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL; 660' FEL NE/SE 1980; FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-32 17-32 17-33 17-34 17-34 17-44 17-44 17-42 17-44 17-44 17-43 18-12 18-12 18-12 18-12 18-22 18-23 18-21 18-24 18-24 18-24 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15732 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31236 43-037-30244 43-037-3555 43-037-31079 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 3030' FEL SW/NE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980; FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL SW/NW 1980' FNL; 2210' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-32 17-32 17-33 17-32 17-34 17-44 17-42 17-44 17-44 17-42 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-44 17-43 18-12 18-12 18-22 18-23 18-21 18-24 18-24 18-31 18-31 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-15728 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31236 43-037-30244 43-037-31079 43-037-31181 43-037-31181 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL; 660' FEL NE/SE 1980; FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL |
| | 16-32 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-23 17-31 17-32 17-33 17-34 17-42 17-42 17-42 17-42 17-42 18-11 18-12 18-12 18-12 18-22 18-23 18-21 18-24 18-31 18-31 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-15728 43-037-15729 43-037-15729 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-16418 43-037-31153 43-037-31236 43-037-31236 43-037-31236 43-037-31236 43-037-31181 43-037-31181 43-037-31181 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980' FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FSL; 660' FEL NW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 1980' FNL; 2210' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SW/SW 810' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1980' FEL |
| | 16-32 16-34 16-41 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-42 17-42 17-42 17-42 17-42 18-11 18-12 18-12 18-12 18-21 18-21 18-21 18-21 18-31 18-31 18-31 18-33 18-34 18-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-31178 43-037-15729 43-037-15729 43-037-15729 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31236 43-037-31236 43-037-31236 43-037-31181 43-037-31181 43-037-31181 43-037-31135 43-037-31135 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL 5W/SE 1980' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL 660 FSL; 660' FEL NE/SE 1980; FNL; 730' FWL NE/SW 1980' FNL; 730' FWL SW/NW 1980' FNL; 730' FWL SW/NW 1980' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SW/SW 810' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL SW/SE 1870' FSL; 1980' FEL SW/SE 780' FSL; 1860 FEL |
| | 16-32 16-34 16-41 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-34 17-42 17-42 17-42 17-42 17-42 17-42 18-11 18-12 18-21 18-21 18-21 18-21 18-21 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-31 19-32 18-33 18-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15735 43-037-31153 43-037-31153 43-037-31153 43-037-31153 43-037-31135 43-037-31135 43-037-15737 43-037-15737 43-037-15737 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/SE 560' FSL; 1845' FEL SW/SE 1980' FSL; 1845' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL 660 FSL; 660' FEL NE/SE 1980; FNL; 730' FWL NE/SW 1980' FNL; 730' FWL SW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SW/SW 810' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL SW/SE 780' FSL; 1860 FEL NE/NE 660' FNL; 660' FEL |
| | 16-32 16-34 16-41 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-42 17-42 17-42 17-42 17-42 18-11 18-12 18-12 18-12 18-21 18-21 18-21 18-21 18-31 18-31 18-31 18-33 18-34 18-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-31178 43-037-15729 43-037-15729 43-037-15729 43-037-15731 43-037-15731 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31236 43-037-31236 43-037-31236 43-037-31181 43-037-31181 43-037-31181 43-037-31135 43-037-31135 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 1845' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 186' FEL 610' FNL; 510' FEL SE/NE 1980' FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SW/SW 810' FSL; 600' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1980' FEL SW/SE 780' FSL; 1860 FEL NE/NE 660' FNL; 660' FEL SE/NE 2120' FNL; 745' FEL |
| | 16-32 16-34 16-41 16-41 16-41 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-44 17-42 17-44 17-42 17-44 17-42 18-12 18-12 18-21 18-21 18-21 18-21 18-21 18-31 19-31 18-31 19-31 18-31 19-31 18-31 18-31 18-31 18-34 18-31 18-34 18-31 18-34 18-31 18-34 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15730 43-037-15731 43-037-15731 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-31183 43-037-31181 43-037-31181 43-037-31181 43-037-15735 43-037-31181 43-037-15736 43-037-31181 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 1845' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 186' FEL SE/NE 1980' FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1980' FEL SW/SE 780' FSL; 1860 FEL NE/NE 660' FNL; 660' FEL SE/NE 2120' FNL; 745' FEL NE/SE 1980' FSL; 660' FEL |
| | 16-32 16-34 16-41 16-41 16-43 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-44 17-42 17-44 17-42 17-44 18-12 18-12 18-21 18-21 18-21 18-31 19-32 18-31 19-32 18-31 18-31 18-31 18-31 18-31 18-31 18-34 18-42 18-42 18-42 18-43 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-15727 43-037-15728 43-037-31170 43-037-31178 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15730 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31153 43-037-31181 43-037-31181 43-037-31181 43-037-15735 43-037-31181 43-037-15737 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-15738 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL SW/SW 660' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 2030' FEL SW/NE 1830' FNL; 1845' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 186' FEL SE/NE 1980' FNL; 660' FEL NE/SE 1980' FSL; 660' FEL NE/SE 1980' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 810' FSL; 600' FWL SE/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1980' FEL SW/SE 780' FSL; 1860 FEL NE/NE 660' FNL; 660' FEL SE/NE 2120' FNL; 745' FEL NE/SE 1980' FSL; 660' FEL |
| | 16-32 16-34 16-41 16-41 16-43 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-44 17-42 17-44 17-42 18-12 18-12 18-12 18-21 18-21 18-21 18-31 18-31 18-31 18-31 18-31 18-31 18-31 18-31 18-44 18-42 18-43 18-44 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31153 43-037-31181 43-037-31181 43-037-31185 43-037-31182 43-037-15738 43-037-15738 43-037-15738 43-037-15737 43-037-31181 43-037-15738 43-037-15738 43-037-15738 43-037-15738 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 1885' FEL NW/NW 720' FNL; 730' FWL NE/SW 1980' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2385' FSL; 2040' FWL SW/SW 3810' FSL; 600' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1860 FEL NE/SE 1980' FSL; 1860 FEL SE/NE 2120' FNL; 745' FEL NE/SE 1980' FSL; 660' FEL SE/SE 660' FSL; 660' FEL |
| | 16-32 16-34 16-34 16-41 16-41 17-11 17-13 17-13 17-22 17-22 17-23 17-31 17-32 17-31 17-32 17-31 17-32 17-31 17-42 17-44 17-42 17-44 17-42 18-11 18-12 18-21 18-22 18-23 18-21 18-24 18-31 18-31 18-34 18-34 18-34 18-34 18-34 18-44 18-43 18-44 18-43 18-44 18-44 18-44 18-43 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15730 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15733 43-037-15735 43-037-31181 43-037-31181 43-037-31181 43-037-15738 43-037-31182 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-15738 43-037-31182 43-037-16419 43-037-31080 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 1882' FWL SW/NW 720' FNL; 730' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2385' FSL; 2040' FWL SW/SW 3810' FSL; 600' FWL SW/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1880' FEL SW/SE 780' FSL; 1980' FEL SW/SE 780' FSL; 1860 FEL NE/NE 660' FNL; 660' FEL SE/NE 2120' FNL; 745' FEL NE/SE 1980' FSL; 660' FEL SE/SE 660' FSL; 660' FEL |
| | 16-32 16-34 16-41 16-41 16-43 17-11 17-13 17-13 17-22 17-23 17-31 17-32 17-33 17-34 17-42 17-44 17-42 17-44 17-42 18-12 18-12 18-12 18-21 18-21 18-21 18-31 18-31 18-31 18-31 18-31 18-31 18-31 18-31 18-44 18-42 18-43 18-44 | 43-037-15723 43-037-15724 43-037-15725 43-037-16415 43-037-31169 43-037-15726 43-037-31133 43-037-15727 43-037-16416 43-037-31170 43-037-15728 43-037-31178 43-037-15729 43-037-31134 43-037-15730 43-037-15731 43-037-15731 43-037-15731 43-037-15733 43-037-16417 43-037-15733 43-037-16418 43-037-31153 43-037-31153 43-037-31181 43-037-31181 43-037-31185 43-037-31182 43-037-15738 43-037-15738 43-037-15738 43-037-15737 43-037-31181 43-037-15738 43-037-15738 43-037-15738 43-037-15738 | 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-355 14-20-603-353 | SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 16, T41S, R24E SEC. 17, T41S, R24E SEC. 18, T41S, R24E | 1980 FNL; 1980' FEL 660 FNL; 1980' FEL 660 FNL; 660 FEL NE/SE 2140 FSL; 820 FEL NW/NW 1075' FNL; 800' FWL SW/NW 1980' FNL; 510' FWL NW/SW 2100' FSL; 660' FWL 510' FNL; 1830' FWL 1980' FNL; 1980' FWL NE/SW 1980' FWL; 1880' FSL NW/NE 500' FNL; 1980' FEL SW/NE 1830' FNL; 2030' FEL NW/SE 1980' FSL; 1845' FEL SW/SE 560' FSL; 1880' FEL 610' FNL; 510' FEL SE/NE 1980; FNL, 660' FEL NE/SE 1980' FSL; 1885' FEL NW/NW 720' FNL; 730' FWL NE/SW 1980' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 1980' FNL; 560' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2200' FNL; 2210' FWL NE/NW 660' FNL; 1882' FWL SW/NW 2385' FSL; 2040' FWL SW/SW 3810' FSL; 600' FWL NE/SW 2385' FSL; 2040' FWL SW/SW 760' FSL; 1980' FWL NW/NE 795' FNL; 2090; FEL SW/NE 2140' FNL; 1830' FEL NW/SE 1870' FSL; 1860 FEL NE/SE 1980' FSL; 1860 FEL SE/NE 2120' FNL; 745' FEL NE/SE 1980' FSL; 660' FEL SE/SE 660' FSL; 660' FEL |

PAId

STATE OF UTAH DIVISION OF OIL, GAS AND MINING

| · · · · · · · · · · · · · · · · · · · | 712, GIG 71110 III | | 5. L | EASE DESIGNAT | ION & SERIAL NO. |
|---|---|--|--|----------------------------------|---|
| SUNDRY NOTICES A (Do not use this form for proposals to di Use "APPLICATION | AND REPORTS (ill or to deepen or plug b FOR PERMIT—" for suc | ack to a different reservoir | | FINDIAN. ALLO VAJO TRIB | ftee or tribe name |
| OIL GAS OTHER | | 444 14 14 14 | l | init agreemen THERFORD | |
| NAME OF OPERATOR MOBIL OIL CORPORATION | 10034-200 | NE CERTI | | ARM OR LEASE | NAME |
| ADDRESS OF OPERATOR | LAND, TX 79702 | SEP 1 3 199 | 3 | VELL NO. | |
| LOCATION OF WELL (Report location clearly and in See also space 17 below.) At surface | accordance with any State req | DIVISION O | | FIELD AND POO GREATER A | NETH |
| At proposed prod. zone | | OIL, GAS & MIN | [11. | SEC., T., R., M., O SURVEY OF | |
| 1. API NO. 15. EL | EVATIONS (Show weether D | F, RT, GR, etc.) | i | COUNTY N JUAN | UTAH |
| s. Check Appropr | iate Box To Indicate N | Nature of Notice, Repor | t or Other D | | |
| | COMPLETE | WATER SHUT-OFF FRACTURE TREATM SHOOTING OR ACID! (Other) | ENT IZING GE OF OP TO TESTING TO THE | REPAIRI ALTERI ABANDO | ING WELL NG CASING DINMENT* on on Well Log form.) |
| APPROX. DATE WORK WILL START | | DATE OF COMPLET | | | |
| 7. DESCRIBE PROPOSED OR COMPLETED starting any proposed work. If well is directing pertinent to this work.) AS OF JULY1, 1993, MOBIL ATTACHED ARE THE INDIVIDUAL | onally drilled, give subsur | face locations and measure * Must be | d and true ver | d by a cement | all markers and zone |
| | | | | | |
| 1 | · | | · · · · · · · · · · · · · · · · · · · | | |
| | | | | | |
| | | | | | |
| | | | | | |
| 3. I hereby certify that the foregoing is true an SIGNED Nilley Odd | | ENV. & REG TECHN | ICIAN | date9 | -8-93 |
| (This space for Federal or State office use) | | | | | |
| APPROVED BY | TITLE | | | DATE | |

| FQRM 11 | | STATE O | | Page _ l _ of _ l |
|---------|--|------------------------------------|-----------------------|-------------------|
| | MONTHLY | OIL AND GA | S DISPOSITION REPOR | Т |
| OPER | Sheffield | | UTAH ACCOUNT NUMB | ER:N7370 |
| | BRIAN-BERRY M-E-P-N-A- MOBIL POB-219031-1807A-REI DALLAS TX-75221-90 | NTWR P.O. DrAWER 31 CORTEZ, CO. | G REPORT PERIOD (MONT | TH/YEAR): 7 / 93 |

| | | | _ | |
|--|--|--|---|--|

AMENDED REPORT [(Highlight Changes)

¥92100/2 401/26.

| ENTITY | PRODUCT | GRAVITY BEGI | BEGINNING | VOLUME | | DISPOSITIONS | | | |
|--------------|---------|--------------|-----------|----------|-------------|--------------|---------------|----------------------|-------------|
| NUMBER | | BTU | INVENTORY | PRODUCED | TRANSPORTED | USED ON SITE | FLARED/VENTED | OTHER | INVENTORY |
| a : : | OIL | | | 177609 | 177609 | 9 | | | |
| 05980 | GAS | | | 72101 | | 5885 | | | |
| | OIL | | | | | | | • | |
| 11174 | GAS | | | | | | | | |
| | OIL | | | · | | | | | |
| | GAS | | | | | | | | |
| | OIL | | | | | - | | | |
| | GAS | | | | | | WAL | EIV | 81 |
| - | OIL | | | | | | No. | -D 4 7 40/ | . " |
| | GAS | | | | | | S | EP 1 3 199 | 3 |
| **** | OIL | | | | · | | D | VISION (GAS & MI | DF NUNIC |
| | GAS | | | | | | | DESCO OC IVIE | ,, |
| | OIL | | | | | , | | | |
| | GAS | | | | | | | | |
| | | TOTALS | | 2/10 | 243825 | EDDE | | | |

COMMENTS: FLEASE NOTE ADDRESS Change, losin ASSU PRODUCTION IN THE FUTURE.

I hereby certify that this report is true and complete to the best of my knowledge.

Telephone Number

Sept 29, 1993

To: Lisha Cordova-Utah Mining FROM: Janice Easley BLM Farmington, NM 505 599-6355

Here is copy of Ratherford Unit Successor Operator.

4 pages including this one.

Eles rathrifold Unit (GC)

PISEIVED BLM

Navajo Area Office P. O. Box 1060 Gallup, New Mexico 87305-1060

670 Freinmeron, NM

ARES/543

JUL 4 0 1993

Mr. G. D. Cox Mobil Exploration and Producing North America, Inc. P. O. Box 633 Midland, Texas 79702

Dear Mr. Cox:

Enclosed for your information and use is the approved Designation of Operator between the Phillips Petroleum Company and Mobil Exploration and Producing North America, Inc. for the Ratherford Unit.

Please note that all other concerned parties will be furnished their copy of the approved document.

Sincerely,

Aliponomine

ACTING Area Director

Enclosure

cc: Bureau of Land Management, Farmington District Office w/enc. TNN, Director, Minerals Department w/enc.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF INDIAN AFFAIRS

RECEIVED BLM

DESIGNATION OF OPERATOR

Phillips Petroleum Company is, on the records of the Bureau of Indian Affairs, operator of the Ratherford Unit,

AREA OFFICE: Window Rock, Arizona LEASE NO: Attached hereto as Exhibit "A" 070 FARMINGTON, NM

and, pursuant to the terms of the Ratherford Unit Agreement, is resigning as Unit Operator effective July 1, 1993, and hereby designates

NAME: Mobil Exploration and Producing North America Inc., duly elected pursuant to the terms of the Ratherford Unit Agreement,

ADDRESS: P. O. Box 633, Midland, Texas 79702

Attn: G. D. Cox

as Operator and local agent, with full authority to act on behalf of the Ratherford Unit lessees in complying with the terms of all leases and regulations applicable thereto and on whom the authorized officer may serve written or oral instructions in securing compliance with the Operating Regulations (43 CFR 3160 and 25 CFR 211 and 212) with respect to (described acreage to which this designation is applicable):

Attached hereto as Exhibit "A"

Bond coverage under 25 CFR 211, 212 or 225 for lease activities conducted by the above named designated operator is under Bond Number 05202782 (attach copy). Evidence of bonding is required prior to the commencement of operations.

It is understood that this designation of operator does not relieve any lessee of responsibility for compliance with the terms of the leases and the Operating Regulations. It is also understood that this designation of operator does not constitute an assignment of any interest in the leases.

In case of default on the part of the designated operator, the lessees will make full and prompt compliance with all regulations, lease terms, stipulations, or orders of the Secretary of the Interior or his representative.

Attached is the appropriate documentation relevant to this document.

The designated operator agrees to promptly notify the authorized officer of any change in the operatorship of said Ratherford Unit.

June <u>//</u>, 1993

Phillips Petroleum Company

Attorney-in-Fact

Mobil Exploration and Producing

North America Inc.

June <u>//</u>, 1993

y: _/5. 0 // pa

ttorney-in-Fact B.D. MARTINY

- the

ACTING

AREA DIRECTOR

DATE

APPROVED BY

TITLE

DATE

APPROVED PURSUANT, TO SECRETARIAL REDELEGATION ORDER 209 DM 8 AND 230 DM 3.

This form does not constitute an information collection as defined by 44 U.S.C. 3502 and therefore does not require OMB approval.

EXHIBIT "A"

ATTACHED TO AND MADE A PART OF DESIGNATION OF SUCCESSOR OPERATOR, RATHERFORD UNIT

EXHIBIT "C"

Revised as of September 29, 19921 SCHEDULE OF TRACT PERCENTAGE PARTICIPATION

| Tract Number | Description of Land | Serial Number and Effective Date of Lease | Tract Percentage Participation |
|-----------------|--|---|--------------------------------------|
| 1 | S/2 Sec. 1, E/2 SE/4 Sec. 2, E/4 Sec. 11, and all of Sec. 12, T-41-S, R-23-E, S.L.H. San Juan County, Utah | 14-20-603-246-A Oct. 5, 1953 | 11.0652565 |
| 2 | SE/4 and W/2 SW/4 Sec. 5, the irregular SW/4 Sec. 6, and all of Sec. 7 and 8, T-41-S, R-24-E, San Juan County, Utah | 14-20-603-368 Oct. 26, 1953 | 14.4159942 |
| 3 | SW/4 of Sec. 4, T-41-S, R-24-E, San Juan County, Utah | 14-20-603-5446 Sept. 1, 1959 | .5763826 |
| 4 | SE/4 Sec. 4, and NE/4 Sec. 9, T-41-s, R-24-E, San Juan County, Utah | 14-20-603-4035 Harch J, 1958 | 1.2587779 |
| 5 | SW/4 of Sec. J, T-41-S, R-24-E, S.L.M., San Juan County, Utah | 14-20-603-5445 Sept. 3, 1959 | . 4667669 |
| 6 | NW/4 of Sec. 9, T-41-S, R-24-E, S.L.M., San Juan County, Utah | 14-20-603-5045 Feb. 4, 1959 | 1.0187043 |
| 7 | NW/4, W/2 NE/4, and SW/4 Sec. 10, SE/4 Sec. 9, T-41-5, R-24-E, San Juan County, Utah | 14-20-603-4043 Feb. 18, 1958 | 3.5097575 |
| 8 | SW/4 Sec. 9, T-41-S, R-24-E, S.L.M. San Juan County, Utah | 14-20-603-5046 Feb. 4, 1959 | 1.1141679 |
| 9 | SE/4 Sec. 10 and S/2 SW/4 Sec. 11 T-41-S, R-24-E, San Juan County, Utah | 14-20-603-4037 Feb. 14, 1958 | 2.6186804 |
| 10 | All of Sec. 13, E/2 Sec. 14, and E/2 SE/4 and N/2 Sec. 24, T-41-5, R-23-E, S.L.M San Juan County, Utah | 14-20-603-247-A Oct. 5, 1953 | 10.3108861 |
| 11 | Sections 17, 18, 19 and 20, T-41-S, R-24-E, San Juan County Utah | 14-20-603-353 Oct. 27, 1953 | 27.3389265 |
| 12 | Sections 15, 16, 21, and NW/4, and W/2 SW/4 Sec. 22, T-41-S, R-24-E, San Juan County, Utah | 14-20-603-355 Oct. 27, 1953 | 14.2819339 |
| 13 | W/2 Section 14, T-41-S, R-24-E, San Juan County, Utah | 14-20-603-370 Oct. 26,1953 | 1.8500847 |
| 14 | N/2 and SE/4, and E/2 SW/4 Sec. 29, NE/4 and E/2 SE/4 and E/2 W/2 irregular Sec. 30, and E/2 NE/4 Sec. 32, T-41-S, R-24-E, San Juan County, Utah | 14-20-603-407 Dec. 10, 1953 | 6.9924969 |
| 15 | NW/4 Sec. 28, T-41-S, R24-E San Juan County, Utah | 14-20-603-409 Dec. 10, 1953 | .9416393 |
| 16 | SE/4 Sec. 3, T-41-S, R-24-E San Juan County, Utah | 14-20-0603-6504 July 11, 1961 | . 5750254 |
| 17 | NE/4 Sec. 3, T-41-5, R-24-E San Juan County, Utah | 14-20-0603-6505 July 11, 1961 | .5449292 |
| 18 | NW/4 Sec. 3, T-41-5, R-24-E San Juan County, Utah | 14-20-0603-6506 July 11, 1961 | .5482788 |
| 19 | NE/4 Sec. 4, T-41-S, R24-E San Juan County, Utah | 14-20-0603-7171 June 11, 1962 | .4720628 |
| 20 | E/2 NW/4 Sec. 4, T-41-S. R-24-E San Juan County, Utah | 14-20-0603-7172 June 11, 1962 | .0992482 |
| | | | |

Division of Oil, Gas and Mining PHONE CONVERSATION DOCUMENTATION FORM

| Route original/copy to: [] Well File | | OPERATOR CHANGE |
|---------------------------------------|---------------------------|-------------------------------|
| (API No.) | | |
| 1. Date of Phone Call:10-6-93 | - Time: 9 | :30 |
| 2. DOGM Employee (name)L. Talked to: | . CORDOVA | (Initiated Call XXX |
| NameGLEN COX | (Initiated Call []) - P | hone No. <u>(915)688-2114</u> |
| of (Company/Organization) | | |
| 3. Topic of Conversation: OPERATO | OR CHANGE FROM PHILLIPS | CO MOBIL "RATHERFORD UNIT". |
| (NEED TO CONFIRM HOW OPERATOR V | VANTS THE WELLS SET UP - | MEPNA AS PERTBIA APPROVAL |
| OR MOBIL OIL CORPORATION AS PER | R SUNDRY DATED 9-8-93?) | |
| | | |
| 4. Highlights of Conversation: | | <u> </u> |
| MR. COX CONFIRMED THAT THE WELL | LS SHOULD BE SET UNDER AG | CCOUNT N7370/MEPNA AS |
| PER BIA APPROVAL, ALSO CONFIRMI | ED THAT PRODUCTION & DIS | POSITION REPORTS WILL NOW |
| BE HANDLED OUT OF THEIR CORTEZ | OFFICE RATHER THAN DALL | AS. |
| MEPNA- | | |
| PO DRAWER G | · | |
| CORTEZ, CO 81321 | | |
| (303)565-2212 | | |
| *ADDRESS CHANGE AFFECTS ALL WEI | LLS CURRENTLY OPERATORED | BY MEPNA, CURRENTLY |
| REPORTED OUT OF DALLAS (MCELMO | | |
| | | |
| | | |
| | • • • | |
| | | |
| | | |

| | of Oil, Gas and Mi | | | | ڒ | Routing: |
|------------------------|--|---|---|---|---|---|
| | R CHANGE HORKS | | | , | | 1 VEC/247-SA () 2-DISTS 8-KIND |
| Attach al Initial e | l documentation re each listed item wh | eceived by the divisionen completed. Write | on regarding this N/A if item is no | cnange. ot applicable. | | 3-VLC 4-RJFV |
| X Chang | ge of Operator | (well sold) | □ Designa | tion of Agent | | 5-11-5 |
| □ Desig | nation of Oper | ator | □ Operato | r Name Change | Only | 6-PV |
| The ope | rator of the w | ell(s) listed bel | ow has changed | (EFFECTIVE | DATE: <u>7-1-9</u> | 3) |
| TO (new | operator) M E | | FROM | (former oper | ator) PHILLIPS | PETROLEUM COMPANY |
| | (address) <u>PO</u> | | | (add | ress) 5525 HWY FARMINGT | ON, NM 87401 |
| | | RTEZ, CO 81321 EN COX (915)688-21 | | | PAT KONK | |
| | | ne <u>(303)565-2212</u> | | | phone (| 505) 599–3452 |
| | | ount no. <u>N7370</u> | · | | account | no. <u>N 0772(A)</u> |
| | | | | | | |
| • | | al page if needed): | | D UNIT (NAVA. | | |
| Name: | **SEE ATTACHED* | ** API: 430 | <u>37<i>3/13/</i></u> Entity | /: Sec | TwpRng | Lease Type: Lease Type: |
| Name:_ | | API: | | /: Sec | TwpRng_ TwpRng_ | |
| Name. | 1 11275 | API:API: | Entity | v:Sec | TwpRng | |
| Name:_ | | API: | Entity | /: Sec | IWPKNG | Lease Type: |
| Name:_ | | API: | Entity | /: Sec | TwpRng | - · · · · · · · · · · · · · · · · · · · |
| Name:_ | | API: | Entity | /: Sec | TwpRng | Lease Type: |
| <u>Lec</u> 1. | operator (Atta (Rule R615-8-1 | 10) Sundry or o ch to this form). | <i>(feg.8-20-93)(6</i> er <u>legal</u> docum | 193 Prod. Ret. 8-16. | -93) | teived from <u>former</u> d from <u>new</u> operator |
| , | The Department operating any | of Commerce has wells in Utah. | been contacted Is company re | d if the new | operator abov | ve is not currently (yes/no) If |
| P | yes, show comp | any file number: | * | | | |
| ŋ | (attach Teleph comments section changes should | hone Documentation of this form take place prion | on Form to t . Management r to completio | his report). review of F n of steps 5 | Make note ederal and In through 9 bel | |
| | listed above. | (0.8.6 wells 10-6-931 | (wiw's 10-26-93 | 3/ | | /IBM) for each well |
| | | s been updated fo | | | | |
| Le 7. | Well file labe | ls have been upda | ated for each | well listed a | ibove . (0 6.6 wells | s 10-6-93) (WIW'S 10-26-4 |
| | for distributi | on to State Lands | s and the Tax | Commission.(| 10-6-937 | count Changes" memo |
| fec 9. | A folder has I placed there f | been set up for tor tor tor | the Operator C ing routing an | hange file, a d processing | and a copy of of the origin | this page has been al documents. |

| PERATOR | CHANGE WORKSHEET (CONTINUED) Initral each item when completed. Write N/A item is not applicable. |
|---------------|---|
| HITTY | REVIEH |
| Lec 1. | (Rule R615-8-7) Entity assignments have been reviewed for all wells listed above. Were entity changes made? (yes/no) (If entity assignments were changed, attach copies of Form 6, Entity Action Form). |
| N/A 2. | State Lands and the Tax Commission have been notified through normal procedures of entity changes. |
| 30ND VI | ERIFICATION (Fee wells only) |
| jec/1. | (Rule R615-3-1) The new operator of any fee lease well listed above has furnished a proper bond. |
| 2. | A copy of this form has been placed in the new and former operators' bond files. |
| 3. | The former operator has requested a release of liability from their bond (yes/no) Today's date 19 If yes, division response was made by letter dated 19 |
| LEASE | INTEREST OHNER NOTIFICATION RESPONSIBILITY |
| 015 | (Rule R615-2-10) The former operator/lessee of any fee lease well listed above has been notified by letter dated 19, of their responsibility to notify any person with an interest in such lease of the change of operator. Documentation of such notification has been requested. |
| <i>1</i> ≥ 2. | Copies of documents have been sent to State Lands for changes involving State leases. |
| FILMIN | G . |
| | All attachments to this form have been microfilmed. Date: |
| FILING | |
| Lee 1. | Copies of all attachments to this form have been filed in each well file. |
| <u>fic2</u> . | The <u>original</u> of this form and the <u>original</u> attachments have been filed in the Operator Change file. |
| COMMEN | ITS |
| 93. | 1006 BIA/Bim Approved 7-9-93. |
| | |
| | |
| | |
| | |
| E71/ | 34–35 |

STATE OF UTAH FORM 10

DIVISION OF OIL, GAS AND MINING
355 West North Temple, 3 Triad, Suite 350, Salt Lake City, UT 84180-1203

Page 20 of 22

MONTHLY OIL AND GAS PRODUCTION REPORT

| OPERATOR NAME AND ADDRESS: | | | UTAH | ACCOUNT NUMBER | N7370 | |
|---|---|-------------|--------|-------------------|--------------------|--------------|
| C/O MOBIL OIL CORP M E P N A PO DRAWER G | | | REPO! | RT PERIOD (MONTH) | /YEAR): 6 / 95 | 5 |
| CORTEZ CO 81321 | | | AMEN | NDED REPORT (H | ighlight Changes) | |
| Well Name | Producing | Well | Days | | Production Volumes | |
| API Number Entity Location | Zone | Status | Oper | OIL(BBL) | GAS(MCF) | WATER(BBL) |
| RATHERFORD UNIT #13-43 | *************************************** | | | | | |
| 4303731131 06280 41S 23E 13 | DSCR | | | | | |
| RATHERFORD UNIT #24-41 | | | | | - | |
| 4303731132 06280 41S 23E 24 | DSCR | | | | ě | |
| RATHERFORD UNIT 17-13 | | | | | | |
| 4303731133 06280 41S 24E 17 | DSCR | | | | | |
| RATHERFORD UNIT #17-33 | | | | | | |
| 4303731134 06280 41S 24E 17 RATHERFORD UNIT #18-33 | DSCR | | | | | |
| 4303731135 06280 41S 24E 18 | DSCR | | | | | |
| RATHERFORD UNIT #1-14 | | | | | | |
| 4303731162 06280 41S 23E 1 | DSCR | | | | | |
| _03731163 06280 41S 24E 7 | DSCR | | | | | |
| RATHERFORD UNIT #7-13 | | | | | | |
| 4303731164 06280 415 24E 7 | DSCR | | | | | |
| RATHERFORD UNIT #7-22 | | | | | | |
| 4303731165 06280 41S 24E 7 | DSCR | | | | | |
| RATHERFORD UNIT #7-24 | | | | | | |
| 4303731166 06280 41S 24E 7 | DSCR | | | | | × |
| RATHERFORD UNIT 7-33 | 16 50 | | | | | |
| 4303731167 06280 41S 24E 7 | IS-DC | | | | | |
| RATHERFORD UNIT #16-13 4303731168 06280 415 24E 16 | חרכט | | | | | |
| 4303731168 06280 41S 24E 16 RATHERFORD UNIT #17-11 | DSCR | | | | | |
| 4303731169 06280 41S 24E 17 | DSCR | | | | | |
| 4303731103 00200 413 242 17 | D3CK 1 | | L | | | |
| • | | | TOTALS | | | |
| | | | [| <u> </u> | <u></u> | |
| | | | | | | |
| | | | | | | |
| · | | | | | | |
|)MMENTS: | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| h / certify that this report is true and complete to | the heat of mi | / knowledge | | Do | te: | |
|) colony due this report is true and complete to | are own or my | MIOWIEUEE | | 134 | ψ. | |
| me and Signature: | | | | т | elephone Number: | |
| | | | | | | |

Division of Oil, Gas and Mining PHONE CONVERSATION DOCUMENTATION FORM

| Rou | Well File (Location) SecTwpRng (API No.) | (Return Date) (To - Initials) | OT LIKE THE CHO |
|-----|--|---|--|
| 1. | Date of Phone Call: 8-3-95 | Time: | |
| 2. | DOGM Employee (name) L. Control Talked to: Name R. J. FIRTH of (Company/Organization) | _ (Initiated Call 🗱) – Pl | hone No. () |
| 3. | | | |
| 4. | Highlights of Conversation: OPERATOR NAME IS BEING CHANGED NORTH AMERICA INC) TO MOBIL EXP THIS TIME TO ALLEVIATE CONFUSIO *SUPERIOR OIL COMPANY MERGED IN | FROM M E P N A (MOBIL EXLOR & PROD. THE NAME CHANGE OF AND AMORE) | APLORATION AND PRODUCING HANGE IS BEING DONE AT DINGST THE GENERAL PUBLIC. |

| | of Oil, Gas and Mining OR CHANGE HORKSHEET | | | | | -PL |
|--------------------------------------|---|---|---|---|--|---------------|
| Attach a Initial | Il documentation received by the division regard each listed item when completed. Write N/A if | ding this change. item is not applica | able. | | 3= DT3 (9-1 | -SJV FILE |
| □ Chan □ Desi | ge of Operator (well sold) gnation of Operator XXX | Designation of Operator Name | Agent Change Only | | 5-RJF V 6-LWP V | |
| The op | erator of the well(s) listed below has | changed (EFFEC | CTIVE DATE: | 8-2-95 |) | |
| TO (ne | w operator) MOBIL EXPLOR & PROD (address) C/O MOBIL OIL CORP PO DRAWER G CORTEZ CO 81321 phone (303) 564-5212 account no. N7370 | FROM (former | operator) (address) | PO DRAWER CORTEZ CO | G 81321 3 > 564-5212 | |
| |) (attach additional page if needed): | | | | | |
| Name:_ Name:_ Name:_ Name:_ | ** SEE ATTACHED ** API: | _ Entity: _ Entity: _ Entity: _ Entity: Entity: | SecTw SecTw SecTw SecTw SecTw | oRng oRng oRng oRng | Lease Type: Lease Type: Lease Type: Lease Type: Lease Type: Lease Type: | |
| 1 | OR CHANGE DOCUMENTATION (Rule R615-8-10) Sundry or other <u>leaders</u> operator (Attach to this form). | | ě | | • | |
| <u>N/A</u> 2. | (Rule R615-8-10) Sundry or other $\underline{\text{lega}}$ (Attach to this form). | <u>l</u> documentation | n has been | received 1 | from <u>new</u> opei | rator |
| <u>µ/А</u> 3. | The Department of Commerce has been coperating any wells in Utah. Is comyes, show company file number: | mpany registere | e new opera d with the | itor above state? (y | is not curre yes/no) | ently _ If |
| <u>N/A</u> 4. | (For Indian and Federal Hells ONLY) (attach Telephone Documentation For comments section of this form. Manachanges should take place prior to con | m to this rep agement review mpletion of ste | ort). Mak of Federa l eps 5 throug | e note o I and Indi gh 9 below | an well oper | rator |
| | Changes have been entered in the Oil listed above. (8-3-95) | | | | BM) for each | well |
| $\frac{1}{2}$ $\frac{1}{6}$. | Cardex file has been updated for each | well listed ab | ove. 8-31. | gr- | | . ' |
| | Well file labels have been updated for | | | | - | |
| <u>Lec</u> 8. | Changes have been included on the more for distribution to State Lands and the | nthly "Operator he Tax Commissi | r, Address, on. <i>(8395)</i> | and Accou | unt Changes" | memo |
| Lico. | A folder has been set up for the Open placed there for reference during roun | rator Change fi ting and proces | ile, and a ssing of the | copy of the original | nis page has documents. | been |

| OPERATOR CHANGE WORKSHEET (CONTINUED) Initial each item when completed. Write N/A if item is not applicable. |
|--|
| ENTITY REVIEW |
| 1. (Rule R615-8-7) Entity assignments have been reviewed for all wells listed above. Wer entity changes made? (yes/no) (If entity assignments were changed, attach copies o Form 6, Entity Action Form). |
| 2. State Lands and the Tax Commission have been notified through normal procedures o entity changes. |
| BOND VERIFICATION (Fee wells only) * No Fee Leese Wells at this time! |
| 1. (Rule R615-3-1) The new operator of any fee lease well listed above has furnished proper bond. |
| 2. A copy of this form has been placed in the new and former operators' bond files. |
| 3. The former operator has requested a release of liability from their bond (yes/no) Today's date 19 If yes, division response was made by letter dated 19 |
| LEASE INTEREST OHNER NOTIFICATION RESPONSIBILITY |
| 1. (Rule R615-2-10) The former operator/lessee of any fee lease well listed above has been notified by letter dated |
| 2. Copies of documents have been sent to State Lands for changes involving State leases. |
| FILMING |
| 1. All attachments to this form have been microfilmed. Date: October 6 1995. |
| FILING |
| 1. Copies of all attachments to this form have been filed in each well file. |
| 2. The <u>original</u> of this form and the <u>original</u> attachments have been filed in the Operator Change file. |
| 950803 WIC F5/Not necessary! |
| |
| |
| |

WE71/34-35



DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Ted Stewart Executive Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) James W. Carter Division Director 801-359-3940 (Fax) 801-538-5319 (TDD)

August 28, 1996

ER Sue MOSLEY THIS WELL HAS NOT BEEN RE-ENTERD CURLENT DIRECTIONAL

Ms. Shirley Robertson Env. & Reg. Technician Mobil Exploration & Production P. O. Box 633 Midland, Texas 79702

Submittal of Directional Surveys and Well Completions Re: Reports

Dear Ms. Robertson:

We have not received the Well Completion Reports or Directional Drilling Surveys for the re-entry of the following wells:

API No. 43-037-31754 T41 5 R238 13 API No. 43-037-31131

Ratherford Unit 19-24 (Multi-Leg)

Ratherford Unit #13-43

API No. 43-037-15755

#21-32

API No. 43-037-15846

Ratherford Unit 12-23

Please submit this information to our office as soon as possible, but no later than September 18, 1996.

Your help in this matter will be greatly appreciated. you have any questions regarding this request, please contact me at (801) 538-5279.

Sincerely,

Vický Dyson

Production Group Supervisor

cc: R. J. Firth

F. R. Matthews

D. T. Staley

L. W. Platt

Well Files



ExxonMobil Production Comp U.S. West P.O. Box 4358 Houston, Texas 77210-4358

June 27, 2001



Mr. Jim Thompson State of Utah, Division of Oil, Gas and Mining 1549 West North Temple Suite 1210 Salt Lake City, UT 84114-5801

Change of Name – Mobil Oil Corporation to ExxonMobil Oil Corporation

Dear Mr. Thompson

Effective June 1, 2001, Mobil Oil Corporation (MOC) changed its name to ExxonMobil Oil Corporation (EMOC). This was a name change only; EMOC is the same corporation as Mobil Oil Corporation, but with a new name. No facility or other asset was transferred from one corporation to another by virtue of the name change. Specifically, EMOC will remain the owner and operator of its existing exploration and production oil and gas properties and facilities, as well as relevant permits.

There is no change to the name of Exxon Mobil Corporation, the ultimate shareholder of EMOC.

Please note the change of name of MOC to ExxonMobil Oil Corporation in your records pertaining to any MOC permits.

The Federal Identification Number for MOC (13-5401570) will remain the same for EMOC.

A copy of the Certification, Bond Rider and a list of wells are attached.

If you have any questions please feel free to call Joel Talavera at 713-431-1010

Charlette J. Darper

Charlotte H. Harper Permitting Supervisor

ExxonMobil Production Company a division of Exxon Mobil Corporation, acting for ExxonMobil Oil Corporation

JUN 29 2001

DIVISION OF OIL, GAS AND MINING



United States Department of the Interior

AVAJOREGION

P.O. Box 1060 Gallup, New Mexico 87305-1060

AUG 3 0 2001

RRES/543

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Charlotte H. Harper, Permitting Supervisor Exxon Mobil Production Company U. S. West P. O. Box 4358 Houston, TX 77210-4358

Dear Ms. Harper:

This is to acknowledge receipt of your company's name change from Mobil Oil Corporation to ExxonMobil Oil Corporation effective June 1, 2001. The receipt of documents includes the Name Change Certification, current listing of Officers and Directors, Listing of Leases, Financial Statement, filing fees of \$75.00 and a copy of the Rider for Bond Number 8027 31 97. There are no other changes.

Please note that we will provide copies of these documents to other concerned parties. If you need further assistance, you may contact Ms. Bertha Spencer, Realty Specialist, at (928) 871-5938.

Sincerely,

CENNI DENETSONE

Regional Realty Officer

cc: BLM, Farmington Field Office w/enclosures
Navajo Nation Minerals Office, Attn: Mr. Akhtar Zaman, Director/w enclosures

| MERERAL RESOURCES ADM J 48 //C NATV AM MEN COORD SOLID BEN TEAM |
|--|
| PETROMENT ISAM Z |
| ALL TEAM LEADERS |
| LAND RESOURCES |
| 1 ILLU |

ExxonMobil Production Company

U.S. West P.O. Box 4358 Houston, Texas 77210-4358


June 27, 2001

Certified Mail Return Receipt Requested

Ms. Genni Denetsone
United States Department of the Interior
Bureau of Indian Affairs, Navajo Region
Real Estate Services
P. O. Box 1060
Gallup, New Mexico 87305-1060
Mail Code 543

100 1/2 100 / Sp 543 100 1

ExonMobil
Production



Change of Name —
Mobil Oil Corporation to
ExxonMobil Oil Corporation

Dear Ms. Denetsone:

Effective June 1, 2001, Mobil Oil Corporation (MOC) changed its name to ExxonMobil Oil Corporation (EMOC). This was a name change only; EMOC is the same corporation as Mobil Oil Corporation, but with a new name. No facility or other asset was transferred from one corporation to another by virtue of the name change. Specifically, EMOC will remain the owner and operator of its existing exploration and production oil and gas properties and facilities, as well as relevant permits.

There is no change to the name of Exxon Mobil Corporation, the ultimate shareholder of EMOC.

Please note the change of name of MOC to ExxonMobil Oil Corporation in your records pertaining to any MOC permits.

The Federal Identification Number for MOC (13-5401570) will remain the same for EMOC.

Attached is the Name Change Certification, Current listing of Officers and Directors, Filing Fee of \$75/-, Listing of Leases, Financial Statement and a copy of the Rider for Bond number 8027 31 97. The original Bond Rider has been sent to Ms. Barbar Davis at your Washington Office.

If you have any questions, please contact Alex Correa at (713) 431-1012.

Very truly yours

Charlotte H. Harper Permitting Supervisor

Attachments

JUL 0 5 2001

NAVAJO REGION OFFICE BRANCH OF REAL ESTATE SERVICES

ExxonMobil Production Company a division of Exxon Mobil Corporation, acting for ExxonMobil Oil Corporation

NOTE: Check forwarded to Ella Isasi

Charlotte U. Harper

Bureau of Indian Affairs
Navajo Region Office
Attn: RRES - Mineral and Mining Section
P.O. Box 1060
Gallup, New Mexico 87305-1060

| Gentlemen | |
|-----------|--|
| | |
| | |

| The current listing of officers and director of | ExxonMobil Oil Corporation (Name of |
|--|--|
| Corporation), of New York | (State) is as follows: |
| President F.A. Risch Vice President K.T. Koonce Secretary F.L. Reid Treasure B.A. Maher | Address 5959 Las Colinas Blvd, Irving, TX 75039 |
| | DIRECTORS |
| Name D.D. Humphreys | DIRECTORS |
| | |
| Name T.P. Townsend | Address 5959 Las Colinas Blvd. Irving, TX 75039 |
| Name _ B.A. Maher | Address 5959 Las Colinas Blvd. Irving, TX 75039 Address 5959 Las Colinas Blvd. Irving, TX 75039 |
| Name F.A. Risch | Address 5959 Las Colinas Blvd. Irving, TX 75039 Address 5959 Las Colinas Blvd. Irving, TX 75039 |
| U | serely, Warrea x Correa |
| and in the custody of Corporation Service | taining to ExxonMobil Oil Corporation (Corporation) s and accounts covering business for the State of Utah (Agent), Phone: 1 (800)927-9800 , 1 South Main Street, Salt Lake City, Utah 84111-2218 |
| (CORPORATE SEAL) | Signature AGENT AND ATTERNEY IN FACT Title |

CERTIFICATION

I, the undersigned Assistant Secretary of ExxonMobil Oil Corporation. (formerly Mobil Oil Corporation), a corporation organized and existing under the laws of the State of New York, United States of America, DO HEREBY CERTIFY, That, the following is a true and exact copy of the resolutions adopted by the Board of Directors on May 22, 2001:

CHANGE OF COMPANY NAME

WHEREAS, the undersigned Directors of the Corporation deem it to be in the best interest of the Corporation to amend the Certificate of Incorporation of the Corporation to change the name and principal office of the Corporation:

NOW THEREFORE BE IT RESOLVED, That Article 1st relating to the corporate name is hereby amended to read as follows:

"1st The corporate name of said Company shall be,

ExxonMobil Oil Corporation",

FURTHER RESOLVED, That the amendment of the Corporation's Certificate of Incorporation referred to in the preceding resolutions be submitted to the sole shareholder of the Corporation entitled to vote thereon for its approval and, if such shareholder gives its written consent, pursuant to Section 803 of the Business Corporation Law of the State of New York, approving such amendment, the proper officers of the Corporation be, and they hereby are, authorized to execute in the name of the Corporation the Certificate of Amendment of Certificate of Incorporation, in the form attached hereto;

FURTHER RESOLVED, That the proper officers of the Corporation be and they hereby are authorized and directed to deliver, file and record in its behalf, the Certificate of Amendment of Certificate of Incorporation, and to take such action as may be deemed necessary or advisable to confirm and make effective in all respects the change of this Company's name to EXXONMOBIL OIL CORPORATION.

WITNESS, my hand and the seal of the Corporation at Irving, Texas, this 8th day of June, 2001.

S. a. Milliam
Assistant Secretary

COUNTY OF DALLAS STATE OF TEXAS

UNITED STATES OF AMERICA

Sworn to and subscribed before me at Irving, Texas, U. S. A. on this the 8th day of June, 2001.

Ganice M. Phillip Notary Public

D. Comment

LISTING OF LEASES OF MOBIL OIL CORPORATION

Lease Number

- 1) 14-20-0603-6504
- 2) 14-20-0603-6505
- 3) 14-20-0603-6506
- 4) 14-20-0603-6508
- 5) 14-20-0603-6509
- 6) 14-20-0603-6510
- 7) 14-20-0603-7171
- 8) 14-20-0603-7172A
- 9) 14-20-600-3530
- 10) 14-20-603-359
- 11) 14-20-603-368
- 12) 14-20-603-370
- 13) 14-20-603-370A
- 14) 14-20-603-372
- 15) 14-20-603-372A
- 16) 14-20-603-4495
- 17) 14-20-603-5447
- 18) 14-20-603-5448
- 19) 14-20-603-5449
- 20) 14-20-603-5450
- 21) 14-20-603-5451

CHUBB GROUP OF INSURANCE COMPANIES

G. Weiler, J. W. Shuth, Suite 1900, Mouston, Texas, 77027-3301
 G. Charles, J. St. 227-4600 r. Fersing st., (713), 297-4760

NW Bond

FEDERAL INSURANCE COMPANY RIDER to be attached to and form a part of

BOND NO 8027 31 97
wherein
Mobil Oil Corporation and Mobil Exploration and Producing U.S., Inc. is
named as Principal and

FEDERAL INSURANCE COMPANY AS SURETY,

in favor of United States of America, Department of the Interior Bureau of Indian Affairs

in the amount of \$150,000.00 bond date: 11/01/65

IT IS HEREBY UNDERSTOOD AND AGREED THAT effective June 1, 2001 the name of the Principal is changed

FROM: Mobil Oil Corporation and Mobil Exploration and Producing U.S., Inc.

TO : ExxonMobil Oil Corporation


All other terms and conditions of this Bond are unchanged.

Signed, sealed and dated this 12th of June, 2001.

ExxonMobil Oil Corporation

FEDERAL INSURANCE COMPANY

Mary Pierson, Attorney-in-fact



POWER OF ATTORNEY

Federal Insurance Company Vigilant Insurance Company **Pacific Indemnity Company**

Attn.: Surety Department 15 Mountain View Road Warren, NJ 07059

Know All by These Presents, That FEDERAL INSURANCE COMPANY, an Indiana corporation, VIGILANT INSURANCE COMPANY, a New York corporation, and PACIFIC INDEMNITY COMPANY, a Wisconsin corporation, do each hereby constitute and appoint R.F. Bobo,

Mary Pierson, Philana Berros, and Jody E. Specht of Houston, Texas----

each as their true and lawful Attorney-in-Fact to execute under such designation in their names and to affix their corporate seals to and deliver for and on their behalf as surety thereon or otherwise, bonds and undertakings and other writings obligatory in the nature thereof (other than ball bonds) given or executed in the course of business, and any instruments amending or attering the same, and consents to the modification or atteration of any

In Witness Whereof, said FEDERAL INSURANCE COMPANY, VIGILANT INSURANCE COMPANY, and PACIFIC INDEMNITY COMPANY have each executed and attested these presents and affixed their corporate seals on this 10th day of May, 2001.

STATE OF NEW JERSEY County of Somersel

UBLIC

County of Somerset

On this

10 th
day of May, 2001

to me known to be Assistant Secretary of FEDERAL INSURANCE COMPANY, VIGILANT INSURANCE COMPANY, and PACIFIC INDEMNITY COMPANY, the companies which executed the foregoing Power of Attorney, and the said Kenneth C. Wendel being by me duly sworn, did depose and say that he is Assistant that the seals affixed to the foregoing Power of Attorney are such corporate seals and were thereto affixed by authority of the By-Laws of said Companies; and that the signature of Frank E. Robertson, subscribed to said Power of Attorney as Assistant Secretary of said Companies; and that the signature of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson, subscribed to said Power of Attorney is in the genuine handwriting of Frank E. Robertson at the said Robertson at the said fright seal

Notary Public State of New Jersey

No. 2231647

Commission Expires Octave 2004 ion

Extract from the By-Laws of FEDERAL INSURANCE COMPANY, VIGILANT INSURANCE COMPANY, and PACIFIC INDEMNITY COMPANY:

"All powers of attorney for and on behalf of the Company may and shall be executed in the name and on behalf of the Company, either by the Chairman or the President or a Vice President or an Assistant Vice President, jointly with the Secretary or an Assistant Secretary, under their respective designations. The signature of such officers may be engraved, printed or lithographed. The signature of each of the following officers: Chairman, President, any Vice President, any Assistant Vice President, any Secretary, any Assistant Secretary and the seal of the Company may be affixed by facsimile to any power of attorney or to any certificate relating thereto appointing Assistant Secretaries or Attorneys-in-Fact for purposes only of executing and attesting bonds and undertakings and other writings obligatory in the nature thereof, and any such power of attorney or certificate bearing such facsimile signature or facsimile seal shall be valid and binding upon the Company and any such power so executed and certified by such facsimile signature and facsimile seal shall be valid and binding upon the Company with respect to any bond or undertaking to which it is attached."

I, Kenneth C. Wendel, Assistant Secretary of FEDERAL INSURANCE COMPANY, VIGILANT INSURANCE COMPANY, and PACIFIC INDEMNITY COMPANY (the "Companies") do hereby certify that

the foregoing extract of the By-Laws of the Companies is true and correct,

the Companies are duly licensed and authorized to transact surely business in all 50 of the United States of America and the District of Columbia and are authorized by the U. S. Treasury Department; further, Federal and Vigilant are licensed in Puerto Rico and the U. S. Virgin Islands, and Federal is licensed in American Samoa, Guam, and each of the Provinces of Canada except Prince Edward Island; and

(iii) the foregoing Power of Attorney is true, correct and in full force and effect.

Given under my hand and seals of said Companies at Warren, NJ this $\underline{}$ 12th







IN THE EVENT YOU WISH TO NOTIFY US OF A CLAIM, VERIFY THE AUTHENTICITY OF THIS BOND OR NOTIFY US OF ANY OTHER MATTER, PLEASE CONTACT US AT ADDRESS LISTED ABOVE, OR BY Fax (908) 903-3656 e-mail: surety@chubb.com

CSC

CSC.

5184334741

06/01 '01 08:46 NO.410 03/09

06/01 '01 09:06 NO.135 02/04

F010601000 187

CERTIFICATE OF AMENDMENT

OF

CERTIFICATE OF INCORPORATION

OF

CSC 45

MOBIL OIL CORPORATION

(Under Section 805 of the Business Corporation Law)

Pursuant to the provisions of Section 805 of the Business Corporation Lew, the undersigned President and Secretary, respectively, of Mobil Oil Corporation hereby certify:

FIRST: That the name of the corporation is MOBIL OIL CORPORATION and that said corporation was incorporated under the name of Standard Oil Company of New York.

SECOND: That the Certificate of Incorporation of the corporation was filed by the Department of State, Albany, New York, on the 10th day of August, 1882.

THIRD: That the amendments to the Certificate of Incorporation effected by this Certificate are as follows:

- (a) Article 1st of the Certificate of Incorporation, relating to the corporate name, is hereby amended to read as follows:
 - "1st The corporate name of said Company shall be,
 ExconMobil Oil Corporation",
- (b) Article 7th of the Certificate of Incorporation, relating to the office of the corporation is hereby amended to read as follows:

The office of the corporation within the State of New York is to be located in the County of Albany. The Company shall have offices at such other places as the Board of Directors may from time to time determine.

CSC ·

5184334741

06/01 '01 08:47 NO.410 04/05

FOURTH: That the amendments to the Certificate of Incorporation were authorized by the Board of Directors followed by the holder of all outstanding shares entitled to wore on amendments to the Certificate of Incorporation by written consent of the sole shareholder dated May 22, 2001.

IN WITNESS WHEREOF, this Certificate has been signed this 22nd Day of May, 2001.

F. A. Risch, President

STATE OF TEXAS
COUNTY OF DALLAS


F. L. REID, being duly sworn, deposes and says that he is the Secretary of MOBIL OIL CORPORATION, the corporation mentioned and described in the foregoing instrument; that he has read and signed the same and that the statements contained therein are true.

F. L. REID, Secretary

SUBSCRIBED AND SWORN TO before me, the undersigned authority, on this the 224 day of May, 2001.

[SEAL]

NOTARY PUBLIC, STATE OF TEXAS



CSC, **CSC**

5184334741

-06/01 01 09:01 NO.411 02/02 -01060100187

C3C 45

CERTIFICATE OF AMENDMENT

OF

MOBIL OIL CORPORATION

Under Section 805 of the Business Corporation Law

STATE OF NEW YORK DEPARTMENT OF STATE

Filed by: EXXONMOBIL CORPORATION

(Name)

FILED JUN 0 1 2001

(LANGE)

TAX \$

· Arc

5959 Les Colines Blvd. (Mailing address)

Irving, TX 75039-2298

(City, State and Zip code)

mes

O E G E IVE O S 2001

JUL 0 5 2001

LINE SERVICES

010601000/95

,TEL=5184334741

06/01'01 08:19

=> CSC

State of New York | State | State | State |

I hereby certify that the annexed copy has been compared with the original document in the custody of the Secretary of State and that the same is a true copy of said original.

Witness my hand and seal of the Department of State on JUN 01 2001



Special Deputy Secretary of State

DOS-1266 (7/00)

OPERATOR CHANGE WORKSHEET

ROUTING

1. GLH 2. CDW / 3. FILE

Change of Operator (Well Sold)

5. If **NO**, the operator was contacted contacted on:

Designation of Agent

X Operator Name Change

Merger

| The operator of the well(s) listed below has changed, | effective: | 06-01-2001 | | | | |
|---|---------------------|---------------------------------|-------------------------|------------|---------------------------------------|----------|
| FROM: (Old Operator): | | TO: (New O _I | perator): | | | |
| MOBIL EXPLORATION & PRODUCTION | 1 | EXXONMOBI | L OIL COF | RPORATIO | N | |
| Address: P O BOX DRAWER "G" | | Address: USV | | | | |
| CORTEZ, CO 81321 | | HOUSTON, T | X 77210-43 | 358 | · · · · · · · · · · · · · · · · · · · | |
| Phone: 1-(970)-564-5212 | | Phone: 1-(713) | | | | |
| Account No. N7370 | | Account No. | | | | |
| CA No. | | Unit: | RATHER | FORD | | |
| WELL(S) | | , | *** | | | |
| | SEC TWN | API NO | ENTITY | LEASE | WELL | WELL |
| NAME | RNG | | NO | TYPE | TYPE | STATUS |
| RATHERFORD UNIT 1-34 | 01-41S-23E | 43-037-16385 | | INDIAN | ow | P |
| RATHERFORD UNIT 1-14 | 01-41S-23E | 43-037-31162 | 6280 | INDIAN | ow | P |
| RATHERFORD 11-41 | | 43-037-31544 | | INDIAN | ow | P |
| RATHERFORD UNIT 11-43 | 11-41S-23E | 43-037-31622 | 6280 | INDIAN | ow | P |
| 12-14 | | 43-037-15844 | | INDIAN | ow | P |
| RATHERFORD UNIT 12-23 (MULTI-LEG) | 12-41S-23E | 43-037-15846 | 6280 | INDIAN | ow | P |
| RATHERFORD UNIT 12-34 | | 43-037-31126 | | INDIAN | ow | P |
| RATHERFORD UNIT 12-12 | | 43-037-31190 | | INDIAN | ow | P |
| RATHERFORD UNIT 12-21 | | 43-037-31201 | | INDIAN | OW | P |
| RATHERFORD UNIT 12-43 | | 43-037-31202 | | INDIAN | ow | P |
| RATHERFORD UNIT 12-32 | | 43-037-31203 | | INDIAN | ow | P |
| RATHERFORD UNIT 13-41 | | 43-037-15856 | | INDIAN | ow | P |
| N DESERT CR 32-13 (13-32) | | 43-037-16406 | | INDIAN | ow | S |
| RATHERFORD UNIT 13-12 | | | 6280 | INDIAN | OW | P |
| RATHERFORD UNIT 13-21 | | 43-037-31128 | | INDIAN | ow | P |
| RATHERFORD UNIT 13-23 | | 43-037-31129 | | INDIAN | OW | P |
| RATHERFORD UNIT 13-34 (RE-ENTRY) | | 43-037-31130 | | INDIAN | OW | P |
| RATHERFORD UNIT 13-43 | | 43-037-31131 | | INDIAN | ow | P |
| RATHERFORD UNIT 13-14 | | 43-037-31589 | | INDIAN | OW | P |
| 14-32 | | 43-037-15858 | | INDIAN | OW | P |
| OPERATOR CHANGES DOCUMENTATION Enter date after each listed item is completed 1. (R649-8-10) Sundry or legal documentation was received | from the FOR | MER operator | on: | 06/29/2003 | 1_ | |
| (R649-8-10) Sundry or legal documentation was received.The new company has been checked through the Departm | | • | 06/29/200 of Corpora | - | oase on: | 04/09/20 |
| 4. Is the new operator registered in the State of Utah: | YES | Business Numb | _ | 579865-014 | | |

N/A

| 6. | Federal and Indian Lease Wells: The BLM and or operator change for all wells listed on Federal or Indian | | as approve BIA-06/01/0 | | name change, | |
|----------|--|-------------------------|---------------------------|--|-----------------------------|------|
| 7. | Federal and Indian Units: The BLM or BIA has approved the successor of unit op | erator for wells | listed on: | 06/01/2001 | | |
| 8. | Federal and Indian Communization Agreem The BLM or BIA has approved the operator for all well | | | N/A | | |
| 9. | Underground Injection Control ("UIC") for the enhanced/secondary recovery unit/project for the | | | | ansfer of Authority to Inje | ect, |
| DA | ATA ENTRY: | | | _/ _ / <u>_ / _ / _ / _ / _ / _ / _ / _ / </u> | | |
| 1. | Changes entered in the Oil and Gas Database on: | 04/12/2002 | | | | |
| 2. | Changes have been entered on the Monthly Operator Cl | hange Spread S | Sheet on: | 04/12/2002 | | |
| 3. | Bond information entered in RBDMS on: | N/A | | | | |
| 4. | Fee wells attached to bond in RBDMS on: | N/A | | | | |
| ST | TATE WELL(S) BOND VERIFICATION: | | | | | |
| 1. | State well(s) covered by Bond Number: | N/A | | | | |
| FF | DERAL WELL(S) BOND VERIFICATION: | | | | | |
| 1. | Federal well(s) covered by Bond Number: | N/A | | | | |
| IN 1. | DIAN WELL(S) BOND VERIFICATION: Indian well(s) covered by Bond Number: | 80273197 | | | | |
| FF | EE WELL(S) BOND VERIFICATION: | | | | | |
| | (R649-3-1) The NEW operator of any fee well(s) listed c | overed by Bond | Number | <u>N/A</u> | | |
| | The FORMER operator has requested a release of liability The Division sent response by letter on: | y from their bon N/A | d on: | N/A | | |
| | EASE INTEREST OWNER NOTIFICATION (R649-2-10) The FORMER operator of the fee wells has of their responsibility to notify all interest owners of this continuous control of the control of their responsibility to notify all interest owners of this control of the co | been contacted | and informed N/A | l by a letter from | the Division | |
| CC | DMMENTS: | | | | | |
| _ | | | | | | |
| | | | | | | |
| | | | | | | |
| | | *** | *** | | 91.43 | |

Division of Oil, Gas and Mining OPERATOR CHANGE WORKSHEET

| ROUTING | : |
|---------|---|
| 1. DJJ | |
| 2. CDW | Ξ |

X Change of Operator (Well Sold)

Operator Name Change/Merger

| The operator of the well(s) listed below has changed, effective: | | 6/1/2006 |
|---|-------------------------------|----------------------------------|
| | TO: (New Operator): | |
| FROM: (Old Operator): N1855-ExxonMobil Oil Corporation | N2700-Resolute Natural | Resources Company |
| PO Box 4358 | 1675 Broadway, | |
| Houston, TX 77210-4358 | Denver, CO 8020 | 2 |
| Phone: 1 (281) 654-1936 | Phone: 1 (303) 534-4600 | |
| CA No. | Unit: | RATHERFORD |
| | | |
| OPERATOR CHANGES DOCUMENTATION | | |
| Enter date after each listed item is completed | | |
| 1. (R649-8-10) Sundry or legal documentation was received from the | e FORMER operator on: | 4/21/2006 |
| 2. (R649-8-10) Sundry or legal documentation was received from the | e NEW operator on: | 4/24/2006 |
| 3. The new company was checked on the Department of Commerc | e, Division of Corporatio | ons Database on: 6/7/2006 |
| 4. Is the new operator registered in the State of Utah: YES | Business Number: | 5733505-0143 |
| 5. If NO , the operator was contacted contacted on: | | |
| 6a. (R649-9-2)Waste Management Plan has been received on: | requested | |
| 6b. Inspections of LA PA state/fee well sites complete on: | n/a | |
| 6c. Reports current for Production/Disposition & Sundries on: | ok | |
| 7. Federal and Indian Lease Wells: The BLM and or the | BIA has approved the | merger, name change, |
| or operator change for all wells listed on Federal or Indian leases | on: BLM | n/a BIAnot yet |
| 8. Federal and Indian Units: | | |
| The BLM or BIA has approved the successor of unit operator for | or wells listed on: | not yet |
| 9. Federal and Indian Communization Agreements (| "CA"): | |
| The BLM or BLA has approved the operator for all wells listed | within a CA on: | n/a |
| 10 Underground Injection Control ("UIC") The I | Division has approved UIC | Form 5, Transfer of Authority to |
| Inject, for the enhanced/secondary recovery unit/project for the | water disposal well(s) listed | d on: 6/12/2006 |
| DATA ENTRY: | | |
| 1 Changes entered in the Oil and Gas Database on: | 6/22/2006 | |
| 2. Changes have been entered on the Monthly Operator Change S | Spread Sheet on: | 6/22/2006 |
| 3. Bond information entered in RBDMS on: | n/a | |
| 4. Fee/State wells attached to bond in RBDMS on: | n/a | |
| 5. Injection Projects to new operator in RBDMS on: | 6/22/2006 n/a | |
| 6. Receipt of Acceptance of Drilling Procedures for APD/New on: | 11/4 | |
| BOND VERIFICATION: | n/a | |
| 1. Federal well(s) covered by Bond Number: | PA002769 | |
| Indian well(s) covered by Bond Number: (R649-3-1) The NEW operator of any fee well(s) listed covered | | n/a |
| a. The FORMER operator has requested a release of liability from t | | - |
| The Division sent response by letter on: | n/a | |
| LEASE INTEREST OWNER NOTIFICATION: | | |
| 4. (R649-2-10) The FORMER operator of the fee wells has been co | ontacted and informed by a | letter from the Division |
| of their responsibility to notify all interest owners of this change | on: n/a | |
| COMMENTS: | | |
| | | |
| | | |

STATE OF LITAH

| _ | EPARTMENT OF NATURAL RESOUR VISION OF OIL, GAS AND MI | | | | SE DESIGNATION AND SERIAL NUMBER: |
|---|--|---|--|-----------------------|--|
| SUNDRY I | NOTICES AND REPORTS | ON WEL | LS | 6. IF IN | DIAN, ALLOTTEE OR TRIBE NAME: ajo Tribe |
| Do not use this form for proposals to drill new | wells, significantly deepen existing wells below curt als. Use APPLICATION FOR PERMIT TO DRILL to | rent bottom-hole dept | h, reenter plugged wells, or to | 7. UNIT | or CA AGREEMENT NAME: |
| 1. TYPE OF WELL OIL WELL | | Jnit Agreeme | | III TORUNINGER | L NAME and NUMBER: attached list |
| 2. NAME OF OPERATOR: Resolute Natural Resources | Company Na760 | | | 3 003 | NUMBER: ched |
| 3. ADDRESS OF OPERATOR: | | 80202 | PHONE NUMBER: (303) 534-4600 | | LD AND POOL, OR WILDCAT: ater Aneth |
| 1675 Broadway, Suite 1950 CITY LOCATION OF WELL FOOTAGES AT SURFACE: See atta QTR/QTR, SECTION, TOWNSHIP, RANGE | ched list | | | COUNT | y: San Juan UTAH |
| 11. CHECK APPRO | OPRIATE BOXES TO INDICAT | E NATURE | OF NOTICE, REPO | RT, O | R OTHER DATA |
| TYPE OF SUBMISSION | | Ţ | YPE OF ACTION | | |
| NOTICE OF INTENT (Submit in Duplicate) Approximate date work will start: | ACIDIZE ALTER CASING CASING REPAIR CHANGE TO PREVIOUS PLANS | DEEPEN FRACTURE NEW CONS OPERATOR | TRUCTION | | REPERFORATE CURRENT FORMATION SIDETRACK TO REPAIR WELL TEMPORARILY ABANDON TUBING REPAIR |
| SUBSEQUENT REPORT (Submit Original Form Only) Date of work completion: | CHANGE TUBING CHANGE WELL NAME CHANGE WELL STATUS COMMINGLE PRODUCING FORMATIONS CONVERT WELL TYPE | RECLAMATI | | | VENT OR FLARE WATER DISPOSAL WATER SHUT-OFF OTHER: |
| 12. DESCRIBE PROPOSED OR COM | IPLETED OPERATIONS. Clearly show all p | pertinent details inc | cluding dates, depths, volum | nes, etc. | |
| Effective June 1, 2006 Exxo Resolute Natural Resource: A list of affected producing UIC Form 5, Transfer of Au | on Mobil Oil Corporation resigns s Company is designated as su and water source wells is attacl | s as operator accessor oper hed. A separa | of the Ratherford U rator of the Ratherfo ate of affected inject | Init. Als ord Unit | t. Ills is being submitted with |
| NAME (PLEASE/PRINT) Dwight E M | Aloro | * | F Regulatory Cool | rdinato | r |
| SIGNATURE LATE | | TIT! | 4/20/2006 | | |
| (This space for State use only) | | | | RE | CEIVED |

APPROVED 6 137 106

Carlene Russell

Division of Oil, Gas and Mining Littons on Reverse Side)

APR 2 4 2006

Earlene Russell, Engineering Technician

DIV. OF OIL, GAS & MINING

| STATE OF UTAH | | FORM 9 |
|---|---|--|
| DEPARTMENT OF NATURAL RESOUR DIVISION OF OIL, GAS AND MIN | | 5. LEASE DESIGNATION AND SERIAL NUMBER: |
| SUNDRY NOTICES AND REPORTS | ON WELLS | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME: Ship Rock |
| Do not use this form for proposals to drill new wells, significantly deepen existing wells below curre drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL for | ent bottom-hole depth, reenter plugged wells, or to rm for such proposals. | 7. UNIT of CA AGREEMENT NAME: UTU68931A |
| A TAPE OF WELL | | 8. WELL NAME and NUMBER: Ratherford |
| | | 9. API NUMBER: |
| 2. NAME OF OPERATOR: ExxonMobil Oil Corporation N / 855 | | attached |
| 3. ADDRESS OF OPERATOR: | PHONE NUMBER: | 10. FIELD AND POOL, OR WILDCAT: Aneth |
| | 77210-4358 (281) 654-1936 | Alleui |
| 4. LOCATION OF WELL FOOTAGES AT SURFACE: | 公理的 宝珠 | COUNTY: San Juan |
| QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN: | | STATE: UTAH |
| 11. CHECK APPROPRIATE BOXES TO INDICAT | E NATURE OF NOTICE REPO | RT. OR OTHER DATA |
| | TYPE OF ACTION | |
| TYPE OF SUBMISSION ACIDIZE | DEEPEN | REPERFORATE CURRENT FORMATION |
| ✓ NOTICE OF INTENT | FRACTURE TREAT | SIDETRACK TO REPAIR WELL |
| (Submit in Duplicate) ALTER CASING Approximate date work will start: CASING REPAIR | NEW CONSTRUCTION | TEMPORARILY ABANDON |
| C SULVESTING PROPERTY OF THE AND | OPERATOR CHANGE | TUBING REPAIR |
| 6/1/2006 CHANGE TO PREVIOUS PLANS CHANGE TUBING | PLUG AND ABANDON | VENT OR FLARE |
| | PLUG BACK | WATER DISPOSAL |
| SUBSEQUENT REPORT (Submit Original Form Only) CHANGE WELL NAME CHANGE WELL STATUS | PRODUCTION (START/RESUME) | WATER SHUT-OFF |
| Date of work completion: COMMINGLE PRODUCING FORMATIONS | RECLAMATION OF WELL SITE | |
| CONVERT WELL TYPE | RECOMPLETE - DIFFERENT FORMATION | |
| | | as atc |
| 12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly show all p | erinent details including dates, deptils, volum | 65, 010 |
| ExxonMobil Oil Corporation is transferring operatorship of Company. All change of operator notices should be made. Attached please find a listing of producers and water source. | effective as of 7:00 AM MST Off | ease to Resolute Natural Resources June 1, 2006. |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | Permitting Supe | rvisor |
| NAME (PLEASE PRINT) Laurie Kilbride | TITLE FERTILLING CUPS | |
| SIGNATURE SAMA: B. Kelbud | DATE 4/19/2006 | |

Division of Oil, Gas and Mining
Earlene Russell, Engineering Technician
(See Instruction

(See Instructions on Reverse Side)

RECEIVED APR 2 1 2006

Ratherford Unit - Producer Well List

| | | | r | -T | T | | _ | Location | 1 | |
|------------|----------|----------------------------------|-----------------------|-------------|--|-----|-----|----------|----------|-----------|
| | i | A D1 # | Chatus | 1 0000 # | 800 | ĪΤ | R | QTR/QTR | | EWFoot |
| Lease | Number | API# | Status | Lease # | Sec | | Λ | GINGIN | 1431 001 | LVVI OOL |
| | <u> </u> | 10007011000001 | Design and the second | 44000000464 | 1 | 415 | 225 | SWSW | 0660FSL | 0660FWL |
| Ratherford | 01-14 | 430373116200S1 | Producing | 1420603246A | 1 | | | SWSE | 1133FSL | 1980FEL |
| Ratherford | 01-34 | 430371638501S1 | SI | 1420603246A | 1 | 4 | | | 0860FNL | 0350FEL |
| Ratherford | 11-41 | 430373154400S1 | Producing | 1420603246A | 11 | | | NENE | | 0660FEL |
| Ratherford | 11-43 | 430373162201S1 | Producing | 1420603246A | 11 | | | NESE | 1980FSL | |
| Ratherford | 12-12 | 430373119000S1 | Producing | 1420603246A | 12 | | | SWNW | 1850FNL | 0660FWL |
| Ratherford | 12-14 | 430371584400S1 | SI | 1420603246A | 12 | | | SWSW | | 4622FEL |
| Ratherford | 12-21 | 430373120100S1 | Producing | 1420603246A | 12 | | | NENW | 0660FNL | 1980FWL |
| Ratherford | 12-23 | 430371584601S1 | Producing | 1420603246A | 12 | | | NESW | | 3300FEL |
| Ratherford | 12-32 | 430373120300S1 | Producing | 1420603246A | 12 | | | SWNE | 1820FNL | - |
| Ratherford | 12-34 | 430373112600S1 | Producing | 1420603246A | 12 | | | SWSE | 0675FSL | 1905FEL |
| Ratherford | 12-43 | 430373120200S1 | SI | 1420603246A | 12 | 41S | 23E | NESE | 2100FSL | 0660FEL |
| | | | | | | | | | | |
| Ratherford | 13-12 | 430373112701S1 | Producing | 1420603247A | 13 | 418 | | SWNW | 1705FNL | 0640FWL |
| Ratherford | 13-14 | 430373158900S1 | Producing | 1420603247A | 13 | 41S | 23E | SWSW | 0660FSL | 0660FWL |
| Ratherford | 13-21 | 430373112801S1 | SI | 1420603247A | 13 | 41S | 23E | NENW | 0660FNL | 1920FWL |
| Ratherford | 13-23 | 430373112900S1 | Producing | 1420603247A | 13 | 418 | 23E | NESW | 1980FSL | 1930FWL |
| Ratherford | 13-34 | 430373113001S1 | Producing | 1420603247A | 13 | 418 | 23E | SWSE | 0660FSL | 1980FEL |
| Ratherford | 13-41 | 430371585601S1 | Producing | 1420603247A | 13 | 418 | 23E | NENE | 660FNL | 660FEL |
| Ratherford | 13-43 | 430373113100S1 | Producing | 1420603247A | 13 | 418 | 23E | NESE | 1700FSL | 0960FEL |
| Ratherford | 14-32 | 430371585801S1 | Producing | 1420603247A | 14 | 418 | 23E | SWNE | 2130FNL | 1830FEL |
| Ratherford | 14-41 | 430373162300S1 | Producing | 1420603247A | 14 | 418 | 23E | NENE | 0521FNL | 0810FEL |
| Ratherford | 24-32 | 430373159300S1 | Producing | 1420603247A | 24 | | | SWNE | 2121FNL | 1846FEL |
| Ratherford | 24-32 | 430373113200S1 | Producing | 1420603247A | 24 | | | NENE | 0660FNL | 0710FEL |
| Ratheriolu | 24-41 | 43037311020001 | i roddollig | 1 120000 | | 1 | | | | |
| Dethorford | 17-11 | 430373116900S1 | Producing | 1420603353 | 17 | 418 | 24E | NWNW | 1075FNL | 0800FWL |
| Ratherford | 17-13 | 43037311090031 430373113301S1 | Producing | 1420603353 | 17 | | | NWSW | 2100FSL | 0660FWL |
| Ratherford | | 43037311301S1 | Producing | 1420603353 | 17 | | | SENW | 1882FNL | 1910FWL |
| Ratherford | 17-22 | 43037311700131 430373104400S1 | Producing | 1420603353 | 17 | | | SESW | 0720FSL | 1980FWL |
| Ratherford | 17-24 | | Producing | 1420603353 | 17 | | | NWNE | 0500FNL | 1980FEL |
| Ratherford | 17-31 | 430373117800S1 | | 1420603353 | 17 | | | NWSE | 1980FSL | 1845FEL |
| Ratherford | 17-33 | 430373113400S1 | Producing | 1420603353 | 17 | 418 | | | 1980FNL | 0660FEL |
| Ratherford | 17-42 | 430373117700S1 | Producing | | 17 | | 24E | | 0660FSL | 0660FEL |
| Ratherford | 17-44 | 430371573201S1 | Producing | 1420603353 | 18 | _ | _ | NWNW | | 0730FWL |
| Ratherford | 18-11 | 430371573300S1 | SI | 1420603353 | _ | | | NWSW | | 0500FWL |
| Ratherford | 18-13 | 430371573401S1 | Producing | 1420603353 | 18 | | | | | 2210FWL |
| Ratherford | 18-22 | 430373123600S1 | Producing | 1420603353 | 18 | | | SENW | | |
| Ratherford | 18-24 | 430373107900S1 | Producing | 1420603353 | 18 | | | SESW | | 1980FWL |
| Ratherford | 18-31 | 430373118101S1 | Producing | 1420603353 | 18 | | | NWNE | | 2090FEL |
| Ratherford | 18-33 | 430373113501S1 | Producing | 1420603353 | 18 | | | NWSE | | 1980FEL |
| Ratherford | 18-42 | 430373118200S1 | Producing | 1420603353 | 18 | | | SENE | | 0745FEL |
| Ratherford | 18-44 | 430373104500S1 | SI | 1420603353 | 18 | | _ | SESE | | 0660FEL |
| Ratherford | 19-11 | 430373108000S1 | Producing | 1420603353 | 19 | | | NWNW | | 0660FWL |
| Ratherford | 19-13 | 430373171900S1 | Producing | 1420603353 | 19 | | _ | NWSW | | 0660FWL |
| Ratherford | 19-22 | 430373104601S1 | Producing | 1420603353 | 19 | | | SENW | | |
| Ratherford | 19-24 | 430373175401S1 | Producing | 1420603353 | 19 | | | SESW | | 1980FWL |
| Ratherford | 19-31 | 430373104701S1 | Producing | 1420603353 | 19 | | | NWNE | 510FNL | 1980FEL |
| Ratherford | 19-33 | 430373104800S1 | Producing | 1420603353 | 19 | 418 | 24E | NWSE | | 1980FEL |
| Ratherford | 19-42 | 430373091600S1 | Producing | 1420603353 | 19 | 418 | 24E | SENE | 1880FNL | . 0660FEL |
| Ratherford | 19-44 | 430373108100S1 | Producing | 1420603353 | 19 | 418 | 24E | SESE | 0660FSL | 0660FEL |
| Ratherford | 19-97 | 430373159600S1 | Producing | 1420603353 | 19 | | | SENE | 2562FNL | . 0030FEL |
| Ratherford | 20-11 | 430373104900S1 | Producing | 1420603353 | 20 | | | NWNW | | . 0660FWL |
| Ratherford | 20-11 | 43037310430051 430373091700S1 | Producing | 1420603353 | 20 | | | NWSW | | 0500FWL |
| Ratherford | 20-13 | 430373091700S1 | Producing | 1420603353 | 20 | | | SENW | | 2090FWL |
| | 20-22 | 43037309300051 | Producing | 1420603353 | 20 | | | SESW | | . 1820FWL |
| Ratherford | ZU-24 | 1 COOOL GOO LCOOF | i roddonig | 12000000 | | | | | | |

Ratherford Unit - Producer Well List

| | T | | | | | | | Locatio | n | Atavat - Allanies - |
|--------------|--------|----------------------------------|-----------|--------------|----------|--------------|-----|---------|--------------------|---------------------|
| Lease | Number | API# | Status | Lease # | Sec | T | R | QTR/QTR | NSFoot | EWFoot |
| | | | | 3 | | | | | | |
| Ratherford | 20-31 | 430373105001S1 | Producing | 1420603353 | 20 | 41S | | NWNE | 0660FNL | 1880FEL |
| Ratherford | 20-33 | 430373093100S1 | Producing | 1420603353 | 20 | 41S | | NWSE | 1910FSL | 2140FEL |
| Ratherford | 20-42 | 430373105100S1 | Producing | 1420603353 | 20 | 418 | | SENE | | 0660FEL |
| Ratherford | 20-44 | 430373091501S1 | Producing | 1420603353 | 20 | 415 | | SESE | | 0760FEL |
| Ratherford | 20-66 | 430373159201S1 | Producing | 1420603353 | 20 | 415 | | SWNW | 1369FNL | 1221FWL |
| Ratherford | 20-68 | 430373159100S1 | Producing | 1420603353 | 20 | 418 | 24E | NWSW | 1615FSL | 1276FWL |
| | | 7= | | | | | | | | 05005)4# |
| Ratherford | 15-12 | 430371571501S1 | Producing | 1420603355 | 15 | | | SWNW | 1820FNL | 0500FWL |
| Ratherford | 15-22 | 430373044900S1 | SI | 1420603355 | 15 | | | SENW | | 2050FWL |
| Ratherford | 15-32 | 430371571700S1 | Producing | 1420603355 | 15 | | | SWNE | 1980FNL | 1980FEL |
| Ratherford | 15-33 | 430371571800S1 | Producing | 1420603355 | 15 | 418 | | NWSE | 1650FSL | 1980FEL |
| Ratherford | 15-41 | 430371571900S1 | TA | 1420603355 | 15 | 41S | | NENE | 0660FNL | 0660FEL |
| Ratherford | 15-42 | 430373044800S1 | Producing | 1420603355 | 15 | 415 | | SENE | 2020FNL | 0820FEL |
| Ratherford | 16-13 | 430373116801S1 | Producing | 1420603355 | 16 | 418 | | NWSW | 1980FSL | 660FWL |
| Ratherford | 16-32 | 430371572300S1 | Producing | 1420603355 | 16 | 418 | | SWNE | 1980FNL | 1980FEL |
| Ratherford | 16-41 | 430371572500S1 | Producing | 1420603355 | 16 | 415 | | NENE | 0660FNL | 0660FEL |
| Ratherford | 16-77 | 430373176800S1 | Producing | 1420603355 | 16 | 418 | | NESW | | 2410FWL |
| Ratherford | 21-23 | 430371375400S1 | Producing | 1420603355 | 21 | 415 | | NESW | 1740FSL | 1740FWL |
| Ratherford | 21-24 | 430373172001S1 | SI | 1420603355 | 21 | | | SESW | 487FSL | 2064FWL |
| Ratherford | 21-32 | 430371575500S1 | SI | 1420603355 | 21 | 418 | | SWNE | 1880FNL | 1980FEL |
| Ratherford | 21-77 | 430373175801S1 | SI | 1420603355 | 21 | 415 | 24E | NWSE | 2511FSL | 2446FEL |
| | | | 100 | | <u> </u> | | L. | | DOCCENII. | DZ40EXA |
| Ratherford | 07-11 | 430373116300S1 | Producing | 1420603368 | 7 | 415 | | NWNW | 0660FNL | 0710FWL |
| Ratherford | 07-13 | 430373116400S1 | Producing | 1420603368 | 7 | 415 | | NWSW | 2110FSL | 0740FWL |
| Ratherford | 07-22 | 430373116500S1 | Producing | 1420603368 | 7 | _ | | SENW | 1980FNL | 1980FWL |
| Ratherford | 07-24 | 430373116600S1 | Producing | 1420603368 | 7 | | | SESW | 0880FSL | 2414FWL 0555FEL |
| Ratherford | 07-44 | 430373118900S1 | SI | 1420603368 | 7 | | | SESE | 0737FSL | 0520FWL |
| Ratherford | 08-12 | 430371599100S1 | Producing | 1420603368 | 8 | - | | SWNW | 1909FNL 0616FNL | 1911FWL |
| Ratherford | 08-21 | 430371599300S1 | Producing | 1420603368 | 8 | 418 | | NENW | 1920FSL | 2055FWL |
| Ratherford | 08-23 | 430371599400S1 | Producing | 1420603368 | 8 | 415 | | NESW | 1980FNL | 1980FEL |
| Ratherford | 08-32 | 430371599500S1 | Producing | 1420603368 | 8 | 415 | | SWNE | 0660FSL | 1980FEL |
| Ratherford | 08-34 | 430371599600S1 | Producing | 1420603368 | 8 | 418 | 24E | SVVSE | UOOUFSL | ISOUFEL |
| | | | | 4.4000024025 | + - | 440 | 245 | SWSE | 0660FSL | 1980FEL |
| Ratherford | 04-34 | 430371616400S1 | Producing | 14206034035 | 4 | 1415 | 245 | JOVVOE | 00001 SL | 13001 LL |
| | | 40007404070004 | Draduaina | 14206034037 | 11 | 1/18 | 245 | SWSW | 0660FSL | 0660FWL |
| Ratherford | 11-14 | 430371616700S1 | Producing | 14206034037 | + '- | 1413 | 246 | | 100001 01 | 00001 112 |
| | | 40007457440004 | SI | 14206034043 | 9 | 419 | 24F | SWSE | 0660FSI | 1980FEL |
| Ratherford | 09-34 | 430371571100S1 | Producing | 14206034043 | 10 | | | SWNW | | 0660FWL |
| Ratherford | 10-12 | 430371571200S1 430371571300S1 | Producing | 14206034043 | 10 | | | swsw | 0510FSL | - |
| Ratherford | 10-14 | 430371571400S1 | TA | 14206034043 | 10 | _ | | SWNE | | 1910FEL |
| Ratherford | 10-32 | 430371371400S1 | TA | 14206034043 | 10 | | | SESE | 0820FSL | |
| Ratherford | 10-44 | 43037304510051 | 11/2 | 14200034040 | 1 10 | + | 1 | | 1 | |
| Dath a fairl | 20.44 | 430373105300S1 | Producing | 1420603407 | 29 | 415 | 24F | NWNW | 0770FNL | 0585FWL |
| Ratherford | 29-11 | | Producing | 1420603407 | 29 | | | SENW | | 1370FWL |
| Ratherford | 29-22 | 430373108200S1 | Producing | 1420603407 | 29 | | | NWNE | | 2140FEL |
| Ratherford | 29-31 | 430373091401S1 | SI | 1420603407 | 29 | | | NWSE | | 1820FEL |
| Ratherford | 29-33 | 430373093200S1 | SI | 1420603407 | 29 | | | SWSE | | 2096FEL |
| Ratherford | 29-34 | 430371534000S1 | SI | 1420603407 | 29 | | | SENE | | 0660FEL |
| Ratherford | 29-42 | 430373093700S1 | Producing | 1420603407 | 30 | | | SWNE | 1975FNL | |
| Ratherford | 30-32 | 430371534200S1 | Producing | 172000707 | + == | 1 | + | | | = 17 |
| Doth and and | 20.44 | 430373044600S1 | Producing | 1420603409 | 28 | 415 | 24F | NWNW | 0520FNL | 0620FWL |
| Ratherford | 28-11 | 43037304460031 | rioducing | 142000700 | + = = | +- | + | + | | 1 |

| | Number | | | | | | | | Locatio | n i | |
|------------|--------|----------------|-----------|-------------|-----|-----|-----|---------|---------|---------|--|
| Lease | | API# | Status | Lease # | Sec | Т | R | QTR/QTR | NSFoot | EWFoot | |
| Ratherford | 09-12 | 430371512600S1 | Producing | 14206035045 | 9 | 415 | 24E | SWNW | 1865FNL | 0780FWL | |
| Ratherford | 09-14 | 430371512700S1 | Producing | 14206035046 | 9 | 418 | 24E | SWSW | 0695FSL | 0695FWL | |
| Ratherford | 04-14 | 430371616300S1 | Producing | 14206035446 | 4 | 41S | 24E | SWSW | 0500FSL | 0660FWL | |
| Ratherford | 03-12 | 430371562000S1 | Producing | 14206036506 | 3 | 418 | 24E | SWNW | 2140FNL | 0660FWL | |

| Water Source Wells (Feb 2006) | | | |
|-------------------------------|-----|------------|--------|
| RU | S1 | 4303700001 | Active |
| RU | S2 | 4303700002 | Active |
| RU | S3 | 4303700003 | Active |
| RU | S4 | 4303700004 | Active |
| RU | S5 | 4303700005 | Active |
| RU | S6 | 4303700006 | Active |
| RU | S7 | 4303700007 | Active |
| RU | S8 | 4303700008 | Active |
| RU | S9 | 4303700009 | Active |
| RU | S10 | 4303700010 | Active |
| RU | S11 | 4303700011 | Active |
| RU | S12 | 4303700012 | Active |
| RU | S13 | 4303700013 | Active |
| RU | S14 | 4303700014 | Active |
| RU | S16 | 4303700016 | Active |
| RU | S17 | 4303700017 | Active |